



JACK CARS

DRIVE WITH ASSURANCE

ESTIMATE

DATE OF ACCIDENT : 27/12/2021
VEHICLE : SKQ1799C
MAKE & MODEL : MERC 250
INSURANCE : SOMPO
SURVEYOR : LKK ADRIAN

PARTS		AMOUNT
1.	FRONT BUMPER <i>Distorted</i>	\$ 1800 ✓ <i>855</i>
2.	FRONT BUMPER BRACKET <i>By d.</i>	\$ 120 ? <i>75</i>
3.	BONNET <i>Repair</i>	\$ 2100 ✓
4.	FENDER - FRONT LEFT <i>tear</i>	\$ 980 ✓ <i>580</i>
5.	DOOR - FRONT LEFT <i>Repair</i>	REPAIR <i>x</i>
6.	SIDE MIRROR - LEFT <i>None</i>	\$ 600 <i>x</i>
7.	HEADLAMP - LEFT <i>Smashed</i>	\$ 2530 ✓ <i>1580</i>
8.	HEADLAMP BRACKET - LEFT <i>By d.</i>	\$ 110 ? ✓ <i>95</i>
9.	MUDGUARD - FRONT LEFT <i>By d.</i>	\$ 180 ? ✓ <i>125</i>
SPECIAL NETT		
1.	CLIPS , SCREWS , RIVETS <i>None</i>	\$ 120 <i>50</i>



JACK CARS

DRIVE WITH ASSURANCE

2.	FRONT BUMPER SENSOR <i>new</i>	\$ 300 +
3.	HEADLAMP PROGRAMMING ? <i>nec</i>	\$ 500 ? <i>120</i>
LABOUR		
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	\$ 1800 <i>800</i>
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	\$ 1000 <i>600</i>
3.	TO CHECK LIGHTING SYSTEM, WIRING & REWIRE	\$ 350 <i>50</i>
4.	TO REMOVE AND REINSTALL BUMPER COMPONENTS	\$ 220 +
6.	TO REMOVE & REINSTALL FRONT SENSORS	\$ 200 <i>60</i>
	PARTS + 15%:	\$ 9,683
	SPECIAL NETT :	\$ 920
	LABOUR :	\$ 3,570
	18,888.00 TOTAL :	\$ 14,173
	7% GST :	\$ 992.11
	GRAND TOTAL :	\$ 15,165.11

Admin King.
H/S 29/12/21 OS Pays
the Authorised.



JACK CARS
DRIVE WITH ASSURANCE

SUPPLEMENTARY

DATE OF ACCIDENT : 27/12/2021
VEHICLE : SKQ1799C
MAKE & MODEL : MERC 250
INSURANCE : SOMPO
SURVEYOR : LKK

PARTS		AMOUNT
1.	HEADLAMP BALLAST - BIG Contaminated	\$ 2,300
2.	HEADLAMP BALLAST - SMALL Contaminated	\$ 1,800
	PARTS +15 %:	\$ 4,715
	TOTAL :	\$ 4,715
	7% GST :	\$ 330.05
	GRAND TOTAL :	\$ 5,045.05

830
580

ADD : 3007 Ubi Road 1 #01-450 S(408701) TEL : 67488824 FAX : 67488834

WEB : www.jackcars.com.sg