



## ESTIMATE

DATE OF ACCIDENT : 27/12/2021
VEHICLE : SKQ1799C
MAKE & MODEL : MERC 250
INSURANCE : SOMPO
SURVEYOR : LKK ADRIAN

PARTS		AMOUNT
1.	FRONT BUMPER <i>Distorted</i>	\$ 1800 ✓
2.	FRONT BUMPER BRACKET ?	\$ 120 ?
3.	BONNET <i>Repair</i>	\$ 2100 ✕
4.	FENDER - FRONT LEFT <i>torn</i>	\$ 980 ✓
5.	DOOR - FRONT LEFT <i>Repair</i>	REPAIR ✕
6.	SIDE MIRROR - LEFT <i>New</i>	\$ 600 ✕
7.	HEADLAMP - LEFT <i>Smashed</i>	\$ 2530 ✓
8.	HEADLAMP BRACKET - LEFT ?	\$ 110 ?
9.	MUDGUARD - FRONT LEFT ?	\$ 180 ?
SPECIAL NETT		
1.	CLIPS , SCREWS , RIVETS <i>New</i>	\$ 120 <i>50</i>



# JACK CARS

DRIVE WITH ASSURANCE

2.	FRONT BUMPER SENSOR <i>Neon</i>	\$ 300 <i>x</i>
3.	HEADLAMP PROGRAMMING <i>?</i>	\$ 500 <i>?</i>
	<b>LABOUR</b>	
1.	TO PUTTY & SPRAY PAINT OF AFFECTED AREA	\$ 1800 <del>800</del>
2.	TO PANEL BEAT & TO REMOVE DAMAGED & NECESSARY PARTS & ATTACHEMENTS; KNOCK, JACK, WELD, RESHAPE AND ALIGN ALL AFFECTED PORTIONS.	\$ 1000 <i>600</i>
3.	TO CHECK LIGHTING SYSTEM, WIRING & REWIRE	\$ 350 <i>50</i>
4.	TO REMOVE AND REINSTALL BUMPER COMPONENTS	\$ 220 <i>x</i>
6.	TO REMOVE & REINSTALL FRONT SENSORS	\$ 200 <i>60</i>
	<b>PARTS + 15%:</b>	\$ 9,683
	<b>SPECIAL NETT :</b>	\$ 920
	<b>LABOUR :</b>	\$ 3,570
	<b>TOTAL :</b>	\$ 14,173
	<b>7% GST :</b>	\$ 992.11
	<b>GRAND TOTAL :</b>	\$15,165.11

*Adrian King.*  
*H/S 29/12/21 OS Pays*  
*Not Authorised.*