

REF: CS/CT/21013251/TXVY3.

POS. REC. BY: Tan JH

ACCIDENT/INVESTIGATION

From: _____ Date: _____

Estimated Cost: _____

OD ☒ TP ☐ WS ☐ TP RES ☐ OD RES ☐ EVA ☐ INV ☐ MV ☐

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: **GBB 5327R**

Policy No. **DMCVSNA00068522101**

Claims No. **SNM21D207562/C02/THAMYL**

Sum Insured: _____ Excess: _____

(Client's Record)

Make/Model: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S
☒	☒

Bal. or Market Value: **\$68K**

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % ☐ Yes ☐ No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Date / Time Action / Instruction

25/5/22 LS \$4300 confirmed by email (Red 13,941.50, 76%)

Date/Time, File Pass to?

☐ Prel. Report
☐ Final Report

Date/Time, File Return to?

2) 26/5/22-typist

Respondent: **Merimen**

Lump Sum / L.S. (LS \$4300)

Veh No:

GBL 668 9L Yr Regn: **2017, July**

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or **Pick up**

Make:

Nissan NP300 Navara 2298

Colour:

Orange

A/C: Insured / Std / NI / NA

Sp. Reading

90323

T/Radio: Insured / Std / NI / NA

Eng/No:

MN TCK 4023 Z 000008

Chassis

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Included / Jammed / Leaked / Burnt or

Brakes: Included / Jammed / Leaked / Burnt or

Mod: ☒ SIRim / STD A/Rim or

Tyre Size:

F: **255/70R16**

R: **255/70R16**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OH / SU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. **7** mm

L/Bal. **7** mm

D.O.A. **23/12/2021**

Carry ballast

Des. of Damages: Frt / Rear / O/S / N/S / JIG / Rooftop or

Rear

R/Bal. **7** mm

L/Bal. **7** mm

D.O.A. **28/12/21**

The U/C / Chassis frame / Body Structure affected due to collision.

Days Of Repair: **6**

Recovery No. of Trn: **2**

Survey Fee:

Transportation:

S + RS \$

Photos

Others


Add Fee:

☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)



AP AUTOMOTIVE SERVICES PTE LTD
 ROC / GST REG NO : 202022890H
 BLOCK 9006
 TAMPINES STREET 93 #01-202
 SINGAPORE 528840
 TEL: 6784 4465
 FAX: 6787 4886

ESTIMATION

DATE :
 VEHICLE : **GBL6689L**
 MAKE / MODEL : **Nissan NP30 Navara**
 CHASIS NO. :

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER	1	\$ 740.00	\$ 740.00
2	REAR BUMPER TOP STEP GARNISH	1	\$ 890.00	\$ 890.00
3	REAR BUMPER CENTER BUTTOM	1	\$ 320.00	\$ 320.00
4	REAR BUMPER REINFORCEMENT	1	\$ 870.00	\$ 870.00
5	REAR NUMBER PLATE LAMP LH	1	\$ 210.00	\$ 210.00
6	REAR BUMPER BRACKET	2	\$ 390.00	\$ 780.00
7	TAIL GATE	1	\$ 1,394.00	\$ 1,394.00
8	TAIL GATE INNER LOCK	2	\$ 257.00	\$ 514.00
9	TAIL GATE LOCK CATCH	2	\$ 65.00	\$ 130.00
10	TAIL GATE HINGH	2	\$ 94.00	\$ 188.00
11	TAIL GATE INNER TIRM COVER	1	\$ 794.00	\$ 794.00
12	TAIL GATE LOGO	1	\$ 85.00	\$ 85.00
13	TAIL GATE EMBLEM <E>	1	\$ 25.00	\$ 25.00
14	TAIL GATE EMBLEM (NP300 I)	1	\$ 75.00	\$ 75.00
15	TAIL GATE EMBKE (NAVARA)	1	\$ 125.00	\$ 125.00
16	TAIL LAMP LH	2	\$ 350.00	\$ 700.00
17	TAIL GATETOP TIRM	1	\$ 280.00	\$ 280.00
18	TAIL GATE TOP MOLDING	1	\$ 430.00	\$ 430.00
19	REAR SIDE PANEL RH	1	\$ 2,390.00	\$ 2,390.00
20	REAR CARGO BED END PANEL	1	\$ 1,210.00	\$ 1,210.00
21	REVERSE CAMERA	1	\$ 890.00	\$ 890.00
22	REVERSE SENSOR	2	\$ 160.00	\$ 320.00
23	REVERSE SENSOR HOLDER	2	\$ 45.00	\$ 90.00
24	REVESRE SENSOR WIRE HARNESS	1	\$ 385.00	\$ 385.00

TOTAL PRICE \$ 13,835.00
 LESS 20% \$ 2,767.00
SUB TOTAL PRICE \$ 11,068.00

bt-
 de-
 de-
 bt-
 dis-
 XR-
 bt-
 x
 x
 Ry
 x
 ney-
 ney-
 ney-
 ney-
 ney-
 chg-
 x
 x
 x
 Ry
 ?
 nw/200
 dis-
 x

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE	1	\$ 80.00	\$ 80.00
2	REAR BUMPER TOP STEP GARNISH CLIP (SET)	1	\$ 80.00	\$ 80.00
3	REAR CARGO BED FROOL BROAD <i>Wooden</i>	1	\$ 550.00	\$ 550.00
4	REAR SIDE PANEL RH SEALANT	1	\$ 150.00	\$ 150.00
5	REAR CARGO BED END PANEL SEALANT	1	\$ 120.00	\$ 120.00

bt-45
2one-
*crn/200
X
X

TOTAL \$ 980.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	700
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,600.00	600
3	TUFF COAT	\$ 80.00	30 30
4	WIRING, BULB CHECKING	\$ 180.00	30 30
5	REMOVE AND REFIX UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60 60
6	CONDUCT WATER TER LEAKAGE TEST	\$ 80.00	X
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	30 30
8	REMOVE AND REFIX FUEL TANK TO FACILITATE REPLACEMENT	\$ 80.00	X
9	REMOVE AND REFIX REAR AIR TANK	\$ 380.00	X
10	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

TOTAL \$4,810.00

TOTAL PARTS COST : \$ 12,048.00
TOTAL LABOUR COST : \$ 4,810.00
TOTAL REPAIR COST : \$ 16,858.00

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

Tanfikh 97495749
WP' 28/12/21 ESPN
tanfikh@lkkauto.com.
6 days
L/S Resurvey after repair

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company

Owner ID: 410G

Vehicle Details

Vehicle No.: GBL6689L

Vehicle to be Exported: No

Intended Deregistration Date: 31 Jan 2022

Vehicle Make: NISSAN

Vehicle Model: NP300 NAVARA D/CAB 7AT

Primary Colour: Orange

Manufacturing Year: 2016

Engine No.: YS23341721A

Chassis No.: MNTCB4D23Z0000088

Maximum Power Output: -

Open Market Value: \$29,139.00

Original Registration Date: 26 Jul 2017

First Registration Date: 26 Jul 2017

Transfer Count: 3

Actual ARF Paid: \$32,795.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 25 Jul 2027

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$40,212.00

COE Rebate Amount: \$22,051.00

Total Rebate Amount: \$22,051.00

The information contained herein is correct as at 27 Dec 2021

OK