



A Subsidiary Of Autobacs Seven Co Ltd. Japan
 8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
 Tel : 6702 1555 Fax : 6702 1444 (Co Reg. No. 201500047H)
 Email : wendy@skauto.com.sg

TO	: CHINA TAIPING (GBE1739X)	DATE	: 28-Dec-21
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: 2XXXXX732N		
VEHICLE DETAILS			
VEHICLE NO.	: SLT8811B		
MODEL / MAKE	: HYUNDAI HYUNDAI		
CHASSIS NO.	: KMHD841CMJU533646		
ACCIDENT DETAIL			
DATE	: 27-Dec-21		
TIME	: 18:05HRS	CONTACT PERSON	: MR. WINSON 91866680

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
1	FRONT BONNET <i>Dented</i>	1	\$ 1,970.70	\$ 1,526.00	1526
2	FRONT BONNET MECHANISM LOCK <i>new</i>	1	\$ 129.90	\$ 129.90	x
3	FRONT BONNET RUBBER GUIDE STOPPER <i>new</i>	4	\$ 10.10	\$ 40.40	+
4	FRONT HEADLAMP LH/RH <i>RH cracked</i>	2	\$ 1,198.80	\$ 2,399.60	1198.80
5	FRONT HEADLAMP LOWER BRACKET LH/RH <i>RH cracked</i>	2	\$ 98.60	\$ 197.20	98.60
6	FRONT FENDER RH <i>Dented</i>	1	\$ 1,227.70	\$ 1,227.70	✓
7	FRONT FENDER INNER SHIELD LH/RH <i>toin RH</i>	2	\$ 85.70	\$ 171.40	85.70
8	FRONT BUMPER <i>Distorted</i>	1	\$ 474.40	\$ 474.40	✓
9	FRONT BUMPER LOWER RUBBER LIP <i>new</i>	1	\$ 61.73	\$ 61.73	x
10	FRONT BUMPER TOP RUBBER SEAL (STICK ON) <i>new</i>	1	\$ 65.30	\$ 65.30	x
11	FRONT BUMPER INNER AIR DUCT LH/RH <i>3M</i>	2	\$ 29.40	\$ 39.40	x
12	FRONT BUMPER FOG LAMP COVER LH/RH <i>3M</i>	2	\$ 28.30	\$ 290.60	x
13	FRONT BUMPER REINFORCEMENT <i>2</i>	1	\$ 695.80	\$ 695.80	x
14	FRONT BUMPER INNER SPONGE <i>new</i>	1	\$ 110.50	\$ 110.50	x
15	FRONT BUMPER LOWER BEAM <i>new</i>	1	\$ 81.00	\$ 81.00	x
16	FRONT BUMPER SIDE RETAINER LH/RH <i>2x Dented</i>	2	\$ 43.61	\$ 87.22	43.61
17	FRONT BUMPER CORNER RETAINER LH/RH <i>new</i>	2	\$ 86.70	\$ 173.40	x
18	FRONT SUPPORT PANEL <i>Cracked</i>	1	\$ 949.30	\$ 949.30	✓
19	FRONT SUPPORT PANEL TOP GARNISH <i>new</i>	1	\$ 179.50	\$ 179.50	x
20	WASHER TANK <i>Del-d</i>	1	\$ 55.30	\$ 55.30	✓
21	WASHER TANK MOTOR <i>new</i>	1	\$ 64.10	\$ 64.10	x
22	AIRCON CONDENSER AIR GUIDE Lh/Rh <i>RH cracked</i>	2	\$ 38.90	\$ 77.80	38.90
TOTAL PRICE				\$ 9,097.55	
LESS -20%				\$ (1,819.51)	
SUB TOTAL PRICE				\$ <u>7,278.04</u>	

569831

4558.64

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BONNET INSULATOR MAT CLIPS SET <i>NH m</i>	1	\$ 50.00	\$ 50.00	+
2	FRONT FENDER INNER SHIELD CLIPS SET LH/RH <i>m</i>	2	\$ 60.00	\$ 120.00	30.
3	FRONT BUMPER CLIPS SET <i>NH</i>	1	\$ 80.00	\$ 80.00	30
3	FRONT BUMPER RIVET SET <i>NH m</i>	1	\$ 60.00	\$ 60.00	+
4	FRONT SUPPORT PANEL TOP GARNISH CLIPS SET <i>NH m</i>	1	\$ 40.00	\$ 40.00	+
5	AIRCON CONDENSER AIR GUIDE CLIPS SET Lh/Rh <i>NH</i>	2	\$ 30.00	\$ 60.00	10.
6	FRONT WHEEL HUP CAP RH <i>NH m</i>	1	\$ 280.00	\$ 280.00	+

TOTAL

70

\$ 690.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,600.00	1000.	
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,400.00	600.	
TO APPLY ANTI-RUST & TUFF KOTE	\$ 105.00	60.	
TO PERFORM LIGHTING & WIRING CHECK	\$ 120.00	30	
TO SEND VEHICLE FOR 3D COMPUTERISED TO PERFORM CHECK & ADJUSTED ALL WHEEL ALIGNMENT	\$ 100.00	+	
TO PERFORM DIAGNOSTIC CHECK & RESET MEMORY FAULT CODE TO IDENTIFICATION STANDARD	\$ 350.00	+	
TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	\$ 120.00	60	
TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	\$ 120.00	60.	

TOTAL

\$ 3,915.00

1810

QUOTATION SUMMARY

PAGE 03

ESTIMATE REPORT

TOTAL PARTS COST	:	\$	7,968.04
TOTAL LABOUR COST	:	\$	3,915.00
TOTAL REPAIR COST	:	\$	11,883.04

APPROVED DETAILS

NO. OF REPAIR DAYS : DAYS

REPAIR UNDER : PART BY PART OR LUMP SUM

DATE / TIME OF SURVEY :

SURVEYED BY / FROM :

CONTACT NUMBER :

EMAIL ADDRESS :

DATE / TIME OF RE-SURVEY :

EXCESS :

Adrian G
L/S 29/12/21.

07 Days.

Total: 6438.64.
L/S: 5.1K. ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: