

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21013256/BPA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7990000002
Claimant Vehicle No :	CB6707J	Insured Vehicle No :	SLX6788C
Date of Loss:	27/12/2021	Nature of Claim:	TP
		Claim No:	9745105609SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	CB6707J	Engine No:	N04CUH14313
Make & Model:	TOYOTA COASTER, 4.0 D (M)	Chassis No:	JTGEP538406000292
Reg. Date:	20/04/2011 (Man. Year: 2011)	Odometer:	262575 km
Colour:	White		
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17.5	Rear Tyre Size:	215/75 R17.5
Front Left Side:	Pirelli 5 mm	Rear Left Side:	Pirelli 5 mm
Front Right Side:	Pirelli 5 mm	Rear Right Side:	Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,206.25	6,442.53	6,763.72	51.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,330.00	3,480.00	3,850.00	52.52
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,536.25	9,922.53	10,613.72	51.68
Approved Total (Overridden) (S\$)		7,950.00		
(S\$)	20,536.25	7,950.00	12,586.25	61.29
+ GST 7.00/7.00% (S\$)	1,437.54	556.50	881.04	61.29
Nett Amount (S\$)	21,973.79	8,506.50	13,467.29	61.29
+ Loss of Use (15.0 x S\$120.00/day) (S\$)		1,800.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		10,313.95		
Global Sum Settlement (S\$)		10,300.00		

INSPECTION

Date of Assignment:	28/12/2021	
Date Inspected:	28/12/2021	Inspected At: 160 SIN MING DRIVE #01-14
Estimated Period of Repair:	12.0 days	Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** CHEW HSIAO TONG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and*

ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	2,916.00 FL	*1,014.54 FL
2	2		*REAR BUMPER BRACKET	Bent	184.00 FL	*167.50 FL
3	1		*REAR BUMPER REINFORCEMENT	No such part	481.00 FL	*- FL
4	2		*TAIL LAMP	Broken	1,378.00 FL	*800.00 FL
5	1		*MUDFLAP	Not Damaged	167.00 FL	*- FL
6	1		*REAR BODY PANEL (RH)	Dented	4,890.00 FL	*3,215.00 FL
7	1		*REAR WINDSCREEN GLASS MOULDING RH	Not Necessary	294.00 FL	*- FL
8	1		*REAR WINDSCREEN GLASS MOULDING LH	Not Necessary	167.00 FL	*- FL
9	1		*REAR DOOR	Dented	2,790.00 FL	*2,790.00 FL
10	1		*REAR DOOR INNER TRIM	Not Necessary	671.00 FL	*- FL
11	1		*REAR DOOR GLASS MOULDING	Necessary	276.00 FL	*165.00 FL
12	1		*REAR DOOR EMERGENCY GLASS MOULDING	Necessary	113.00 FL	*113.00 FL
13	1		*REAR BODY PANEL LOGO	No	116.00 FL	*45.00 FL
14	1		*REAR END PANEL	Not Necessary	846.00 FL	*- FL
15	1		*REAR END PANEL GARNISH	Not Damaged	346.00 FL	*- FL
16	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
17	1		*REAR BUMPER CLIPS	No such part	50.00 FS	*- FS
18	1		*REVERSE SENSOR WITH MODULE	Not Necessary	200.00 FS	*- FS
19	1		*REAR DOOR SEALANT	Necessary	100.00 FS	*40.00 FS
20	1		*REAR DOOR TRIMBOARD CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*REAR DOOR SEALANT	Repeated	100.00 FS	*- FS
22	1		*REAR DOOR TRIMBOARD CLIPS	Repeated	50.00 FS	*- FS
23	1		*REAR WINDSCREEN SEALANT (3 PCS)	Necessary	300.00 FS	*80.00 FS
24	3		*REAR WINDSCREEN INNER SEAL	Not Necessary	240.00 FS	*- FS
25	3		*REAR WINDSCREEN PRIMER & CLEANER	Not Necessary	180.00 FS	*- FS
26	1		*EMERGENCY DOOR STICKER	Necessary	50.00 FS	*30.00 FS
27	1		*STICKER 60KM/H	No	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	17,115.00	8,520.04
- List Item Discount on L Items 25.00/25.00% (\$)	3,908.75	2,077.51
Total Parts (\$)	13,206.25	6,442.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R REAR DOOR COMPONENT	New	150.00	80.00
2	R&R REAR DOOR GLASS	New	200.00	80.00
3	R&R REAR WINDSCREEN	New	350.00	120.00
4	R&R REAR BUMPER REVERSE SENSOR	New	150.00	0.00
5	CHECK WIRING	New	100.00	0.00
6	UPHOLSTERY	New	300.00	0.00
7	DIAGNOSTIC RESET FAULT CODE	New	300.00	0.00
8	CONDUCT WATER LEAK TEST	New	180.00	0.00
9	PANEL BEATING	New	3,200.00	1,600.00
10	RUST PROOFING	New	200.00	0.00
11	SPRAY PAINTING	New	2,200.00	1,600.00
Gross Labour Cost (\$\$)			7,330.00	3,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >