

SJE : _____
 Date of Survey : _____
 Date of ReSurvey: _____
 Contacts : _____

Vehicle Nos : **CB 6707 J**
 Model : Toyota Coaster
 Year : _____
 Chassis No : _____

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____ Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Rear bumper	1	\$ 2,916.00	\$ 1014.54 2,916.00
2	Rear bumper bracket	2	\$ 83.75 92.00	\$ 167.50 184.00
3	Rear bumper reinforcent	1	\$ 481.00	\$ 481.00
4	Tail lamp	2	\$ 400.00 689.00	\$ 800.00 1,378.00
5	Mudflap	1	\$ 167.00	\$ 167.00
6	Rear body panel	1	\$ 4,890.00	\$ 3215.00 4,890.00
7	Rear windscreen glass moulding RH	1	\$ 294.00	\$ 294.00
8	Rear windscreen glass moulding LH	1	\$ 167.00	\$ 167.00
9	Rear door	1	\$ 2,790.00	\$ ✓ 2,790.00
10	Rear door inner trim	1	\$ 671.00	\$ 671.00
11	Rear door glass moulding	1	\$ 276.00	\$ 165.00 276.00
12	Rear door emergency glass moulding	1	\$ 113.00	\$ ✓ 113.00
13	Rear body panel logo	1	\$ 116.00	\$ 45.00 116.00
14	Rear end panel	1	\$ 846.00	\$ 846.00
15	Rear end panel garnish	1	\$ 346.00	\$ 346.00

BTV
BTV
NSX
BRV
NDX
DDV
NNX
NECV
NECV
NNX
NDX

Survey 28/12/2021
 Resurvey 29/12/2021
 1345 hrs
 1400hrs
 Train in Train in
 Lump sum repair
 Repair days 12

Parts Sub Total :	\$ 8310.04	15,635.00
Discount 25% :	\$ 2077.51	3,908.75
PARTS TOTAL :	\$ 6232.53	11,726.25

Parts 6232.53
 SN 210.00
 Labour 3480.00
 9922.53
 @ 20% 1984.51
 7938.02

LS 7950/r

Train in
 10/1/2022

Customers hence notify
 of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature: _____
 Date: _____

Nos.	SPECIAL NETT ITEMS	Qty	Unit S\$	TOTAL S\$	
1	Sundries	1	\$ 80.00	\$ 80.00	NN
2	Rear bumper clips	1	\$ 50.00	\$ 50.00	NSX
3	Reverse sensor with module	1	\$ 200.00	\$ 200.00	NN
4	Rear door sealant	1	\$ 100.00	\$ 100.00 40.00	NE
5	Rear door trimboard clips	1	\$ 50.00	\$ 50.00 30.00	NEC
6	Rear door sealant	1	\$ 100.00	\$ 100.00	RPT
7	Rear door trimboard clips	1	\$ 50.00	\$ 50.00	RPT
8	Rear windscreen sealant	3	\$ 100.00	\$ 300.00 80.00	NEC
9	Rear windscreen inner seal	3	\$ 80.00	\$ 240.00	NN
10	Rear windscreen primer & cleaner	3	\$ 60.00	\$ 180.00	NAL
11	Emergency door sticker	1	\$ 50.00	\$ 50.00 30.00	} NEC
12	Sticker "60km/h"	1	\$ 80.00	\$ 80.00 30.00	
SPECIAL NETT TOTAL :				\$ 210.00	1,480.00

Nos.	LABOUR	S\$	
1	R&R rear door component	\$ 150.00 80.00	-
2	R&R rear door glass	\$ 200.00 80.00	-
3	R&R rear windscreen	\$ 350.00 120.00	-
4	R&R rear bumper reverse sensor	\$ 150.00	NN
5	Check wiring	\$ 100.00	} NN
6	Upholstery	\$ 300.00	
7	Diagnostic reset fault code	\$ 300.00	
8	Conduct water leak test	\$ 180.00	} NN
9	Panel beating	\$ 3,200.00 1600.00	
10	Rust proofing	\$ 200.00	NN
11	Spray painting	\$ 2,200.00 1600.00	
LABOUR TOTAL :		\$ 3480.00	7,330.00

PARTS TOTAL : \$ 11,726.25
 SPECIAL NETT TOTAL : \$ 1,480.00
 LABOUR TOTAL : \$ 7,330.00
GRAND TOTAL : \$ 20,536.25

The Auto Consultants hence notify the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date: