



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | |
|--|---|--|------------|
| HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY | | Ref: CC4/ASM21013257/Upa3q2 Date: 17/04/2023 Code: HSB | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | |
| Insured Veh. | SH 9513K | Veh. Inspected | SJS 4326R |
| Policy No. | P2426680 | Coverage (\$) | 0.00 |
| Claim No. | S1M03PIC | Excess (\$) | 0.00 |
| Assign From | | Assign Date | 28/12/2021 |
| 2. Vehicle Particulars & Condition | | | |
| Make & Model | TOYOTA VIOS (A) | c.c | 1497 |
| Engine No. | HIDDEN | Year of Reg. | 2009 |
| Chassis No. | MR053HY9305126074 | Colour | WHITE |
| Odometer | 223181 KM | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |
| 3. Conditions of Tyres | | | |
| | Size | Make | Balance |
| R/H Front Tyre | 205/50 R16 | ULTRA | 6 mm |
| L/H Front Tyre | 205/50 R16 | ULTRA | 6 mm |
| R/H Rear Tyre | 205/50 R16 | ULTRA | 6 mm |
| L/H Rear Tyre | 205/50 R16 | ULTRA | 6 mm |
| 4. Description of Damages | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | |
| 5. General Information | | | |
| Accident Date | 27/12/2021 | Inspection Date | 28/12/2021 |
| Survey held at | FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883 | | |
| 5a. Remarks | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |
| 5b. Estimate Days of Repair | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 4 Working Days | |