

REPAIR ESTIMATE

INSURANCE: III

VEHICLE NO.: SHD 3952S


Description	Qty	List Price	Amount
Frt Door(LH) <i>Deval</i>	1	\$ 1,797.20	\$ 1,797.20
Frt Door Rubber <i>Hue</i>	1	\$ 250.00	\$ 250.00
Front Door Regulator (LH) <i>mainly broken</i>	1	\$ 750.40	\$ 750.40
Front Door Power Motor, LH <i>Hue</i>	1	\$ 689.20	\$ 689.20
Front Door Inner Lock (LH) <i>Down</i>	1	\$ 385.60	\$ 385.60
Front Door Outer Handle (LH) <i>Regu</i>	1	\$ 234.80	\$ 234.80
Front Door Mirror ASSY (LH) <i>Gate Hue</i>	1	\$ 1,691.70	\$ 1,691.70
Front Door Trim Board (LH) <i>mainly broken</i>	1	\$ 796.80	\$ 796.80
Front Door Protector(LH) <i>kt / cut</i>	1	\$ 186.20	\$ 186.20
Rear Door (LH) <i>Deval</i>	1	\$ 1,789.90	\$ 1,789.90
Rear Door Rubber(LH) <i>Hue</i>	1	\$ 280.00	\$ 280.00
Rear Door Outer Handle (LH) <i>Hue</i>	1	\$ 124.80	\$ 124.80
Rear Door Gear/Regulator(LH) <i>Hue mainly broken</i>	1	\$ 367.84	\$ 367.84
Rear Door Power Motor (LH) <i>Hue</i>	1	\$ 256.80	\$ 256.80
Rear Door Lock Assy <i>Hue</i>	1	\$ 306.40	\$ 306.40
Rear Door Hinge Upper (LH) <i>Hue</i>	1	\$ 173.88	\$ 173.88
Rear Door Hinge Lower (LH) <i>Hue</i>	1	\$ 170.50	\$ 170.50
Rear Door Check(LH) <i>Hue</i>	1	\$ 85.92	\$ 85.92
Rear Door Trim Board (LH) <i>Hue mainly broken</i>	1	\$ 613.60	\$ 613.60
Rear Door Protector(LH) <i>cut / Hue</i>	1	\$ 166.20	\$ 166.20
Door Centre Pillar Outer (LH) <i>Deval</i>	1	\$ 3,764.90	\$ 3,764.90
Rocker Panel Outer Garnish <i>cut</i>	1	\$ 715.60	\$ 715.60
Rocker Panel Outer Garnish clip <i>Hue</i>	1	\$ 65.00	\$ 65.00
SUB TOTAL			\$ 15,663.24
LESS 20%			\$ 3,132.65
DISCOUNTED TOTAL			\$ 12,530.59
Front Door Comfort Logo (LH) <i>Hue</i> SN	1	\$ 75.00	\$ 75.00
Rear Door Tel No.Sticker(LH) <i>Hue HIF</i> SN	1	\$ 10.00	\$ 10.00
Rear Door Comfortdelgro & Apps Sticker(LH) <i>Hue</i> SN	1	\$ 80.00	\$ 80.00
SUB TOTAL			\$ 165.00
Labour Charge			
Panel Beating	1	\$1,800.00	\$1,800.00
Spray Painting Charge	1	\$1,600.00	\$1,600.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00
Transfer of Door Mechanism FRONT	1	\$80.00	\$80.00

Re-set Frt Power Window System	1	\$200.00	\$200.00
Transfer of Door Mechanism REAR	1	\$80.00	\$80.00
Re-set Rear Power Window System	1	\$200.00	\$200.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$4,940.00
ESTIMATE TOTAL			\$ 17,635.59


42
 60/-
 44
 44
 1560.00
 =

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

29/12/2021 @ 1000hrs
 N/A Andrew
 2/3 hrs 8 days.


 Ryan

LKK Audi



10,952.34

4/s 9,850/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: