

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/TP/1073/2021/JT  
**DATE** : 30-Dec-21  
**WIP** : 60800

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 31/12/21**

**YOUR INSURED VEH NO : SLG 5704 R**

**India International Insurance Pte Ltd**

64 Cecil Street

#04-00/05-00 IOB Building

Singapore 049711

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**OWNER'S NAME** : MR POH BOON PING  
**ADDRESS** : BLK 519A TAMPINES CENTRAL  
#10-17  
SINGAPORE 521519  
**TELEPHONE** : HP +65 96469245  
**TYPE OF CLAIM** : THIRD PARTY CLAIM  
**POLICY NO** : DMPPHQ21-008827  
**VEHICLE NO** : **SMG 5516 E**  
**MODEL CODE** : AUDI A5 SB 2.0 TFSI  
**MODEL YEAR** : 24/12/2018  
**ENGINE NO** : CVK 073943  
**CHASSIS NO** : WAUZZZF55KA013468  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 26-Dec-21  
**PLACE OF ACCIDENT** : BEDOK NORTH AVE 3 JUNCTION  
OF BEDOK NORTH STREET



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 5516 E**

| S/N                         | NATURE OF JOBS   | ESTIMATED CHARGES    | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--|----------------------|----------------------------|
| 1                           | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.                        | S/N \$ 360.00        | ✓                          |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 1,200.00          | 820                        |
| 3                           | TO RESPRAY REAR BUMPER.  | \$ 1,000.00          | 820                        |
| 4                           | TO CARRY OUT DIAGNOSTIC CHECK.   | S/N \$ 192.00        | ✓                          |
| <b>TOTAL LABOUR CHARGES</b> |  | <b>: \$ 2,752.00</b> |                            |



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5516 E

|                             |  |     | DAMAGED PARTS & PRICES |         |  |
|-----------------------------|--|-----|------------------------|---------|--|
| S/N                         | PARTS DESCRIPTION                                  | QTY | S/NETT                 | REMARKS |  |
| 1                           | REAR BUMPER <i>Defunct.</i>                        | 1   | \$ 2,504.00            | ✓       |  |
| 2                           | REAR BUMPER FIXING PARTS <i>new</i>                | 1   | \$ 165.00              | +       |  |
| 3                           | REAR BUMPER SECURING STRIP <i>new</i>              | 1   | \$ 223.00              | ✓       |  |
| 4                           | REAR BUMPER CHROME TRIM <i>cut</i>                 | 1   | \$ 1,016.00            | ✓       |  |
| 5                           | REAR LIGHT REFLECTOR - LH / RH <i>new</i>          | 2   | \$ 82.00               | X       |  |
| 6                           | REAR BUMPER REINFORCMENT BEAM <i>new</i>           | 1   | \$ 940.00              | X       |  |
| 7                           | REAR BUMPER SEAL <i>new</i>                        | 2   | \$ 28.00               | +       |  |
| 8                           | REAR BUMPER GUIDE SECTION - LH / RH <i>new</i>     | 2   | \$ 46.00               | +       |  |
| 9                           | REAR PARKING AID SENSOR - INNER / OUTER <i>new</i> | 2   | TBC                    | +       |  |
| 10                          | REAR PARKING AID SENSOR SEAL RING <i>new</i>       | 4   | \$ 14.00               | +       |  |
| 11                          | SUNDRIES   |     | \$ 200.00              | ?       |  |
| <b>TOTAL SPARE PARTS</b>    |  | :   | \$ 5,218.00            |         |  |
| <b>TOTAL LABOUR CHARGES</b> |  | :   | \$ 2,752.00            |         |  |
| <b>GRAND TOTAL</b>          |  | :   | \$ 7,970.00            |         |  |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.



# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME  
SURVEYED DATE  
AUTHORISED DATE  
EXCESS COST  
LIABILITY  
REMARKS

:  
:  
:  
:  
:  
:

Adrian  
31/10/21

Not Authorised, 03 Days

(Before Paint  
Required)

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE  
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER  
LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF  
REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO  
MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR  
APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT