

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/1073/2021/JT
DATE : 30-Dec-21
WIP : 60800

Cecilia.

\$5894.50

Before Paint Photos Required

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 31/12/21

YOUR INSURED VEH NO : SLG 5704 R

India International Insurance Pte Ltd

64 Cecil Street

#04-00/05-00 IOB Building

Singapore 049711

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR POH BOON PING
ADDRESS : BLK 519A TAMPINES CENTRAL
#10-17
SINGAPORE 521519
TELEPHONE : HP +65 96469245
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : DMPPHQ21-008827
VEHICLE NO : **SMG 5516 E**
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 24/12/2018
ENGINE NO : CVK 073943
CHASSIS NO : WAUZZZF55KA013468
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 26-Dec-21
PLACE OF ACCIDENT : BEDOK NORTH AVE 3 JUNCTION
OF BEDOK NORTH STREET

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408695

TEL: 6365 2323 FAX: 6841 1183

EMAIL: NDRA.KHAJ@PREMIUMAUTO.COM.SG T.CLA@MSB.PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG S516 E

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.	S/N \$ 360.00 ✓	
2	TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,200.00 <i>SW</i>	
3	TO RESPRAY REAR BUMPER.	\$ 1,000.00 <i>SW</i>	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: \$ 2,752.00	

PREMIUM AUTOMOBILES



51, UBI ROAD 2, SINGAPORE 408695
TEL: 6860 2327 FAX: 6811 1193
EMAIL: NORA.KHUT@PREMIUMAUTOS.COM.SG / CLAIMING@PREMIUMAUTOS.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5516 E

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>ok</i>	1 S	2,504.00	✓
2	REAR BUMPER FIXING PARTS <i>ok</i>	1 S	165.00	✓
3	REAR BUMPER SECURING STRIP <i>ok</i>	1 S	223.00	✓ 222.50
4	REAR BUMPER CHROME TRIM <i>ok</i>	1 S	1,016.00	✓
5	REAR LIGHT REFLECTOR - LH / RH <i>ok</i>	2 S	82.00	✓
6	REAR BUMPER REINFORCEMENT BEAM <i>ok</i>	1 S	940.00	✓
7	REAR BUMPER SEAL <i>ok</i>	2 S	28.00	✓
8	REAR BUMPER GUIDE SECTION - LH / RH <i>ok</i>	2 S	46.00	✓
9	REAR PARKING AID SENSOR - INNER / OUTER <i>ok</i>	2	TBC	✓
10	REAR PARKING AID SENSOR SEAL RING <i>ok</i>	4 S	14.00	✓
11	SUNDRIES <i>ok</i>	S	200.00	✗
TOTAL SPARE PARTS		:	\$ 5,218.00	
TOTAL LABOUR CHARGES		:	\$ 2,752.00	
GRAND TOTAL		:	\$ 7,970.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 67662123 FAX: 6341 1183

EMAIL: NORA.KHAI@PREMIUM-AUTO.COM.SG CLAIMS@PREMIUM-AUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Adrian
31/10/11

Not Authorised, 23 Days
H.S.

Bebe Paint
Required

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT