

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/TP/1073/2021/JT  
DATE : 30-Dec-21  
WIP : 60800

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE SURVEY 31/12/21**

**YOUR INSURED VEH NO : SLG 5704 R**

**India International Insurance Pte Ltd**

64 Cecil Street

#04-00/05-00 IOB Building

Singapore 049711

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

Hi Adrian,

**3 days - ok - Jy - 31 Jan 22**

OWNER'S NAME : MR POH BOON PING  
ADDRESS : BLK 519A TAMPINES CENTRAL  
#10-17  
SINGAPORE 521519  
TELEPHONE : HP +65 96469245  
TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : DMPPHQ21-008827  
VEHICLE NO : **SMG 5516 E**  
MODEL CODE : AUDI A5 SB 2.0 TFSI  
MODEL YEAR : 24/12/2018  
ENGINE NO : CVK 073943  
CHASSIS NO : WAUZZZF55KA013468  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 26-Dec-21  
PLACE OF ACCIDENT : BEDOK NORTH AVE 3 JUNCTION  
OF BEDOK NORTH STREET

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMG 5516 E**

| S/N                         | NATURE OF JOBS                                                                                           |        | ESTIMATED<br>CHARGES |    | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|----------------------------------------------------------------------------------------------------------|--------|----------------------|----|-------------------------------|
| 1                           | TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION.                        | S/N \$ | 360.00               | \$ | 360.00                        |
| 2                           | TO DISMANTLE AND RENEW REAR BUMPER. RE-ORGANIZE CRASH MANGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$     | 1,200.00             | \$ | 800.00                        |
| 3                           | TO RESPRAY REAR BUMPER.                                                                                  | \$     | 1,000.00             | \$ | 800.00                        |
| 4                           | TO CARRY OUT DIAGNOSTIC CHECK.                                                                           | S/N \$ | 192.00               | \$ | 192.00                        |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                          | :      | <b>\$ 2,752.00</b>   | \$ | <b>2,152.00</b>               |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA KHAI@PREMIUMAUTO.COM SG / CLAIMS@PREMIUMAUTO.COM SG

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMG 5516 E**

|                             |                                         |     | DAMAGED PARTS & PRICES |                    |
|-----------------------------|-----------------------------------------|-----|------------------------|--------------------|
| S/N                         | PARTS DESCRIPTION                       | QTY | S/NETT                 | REMARKS            |
| 1                           | REAR BUMPER                             | 1   | \$ 2,504.00            | \$ 2,504.00        |
| 2                           | REAR BUMPER FIXING PARTS                | 1   | \$ 165.00              |                    |
| 3                           | REAR BUMPER SECURING STRIP              | 1   | \$ 223.00              | \$ 222.50          |
| 4                           | REAR BUMPER CHROME TRIM                 | 1   | \$ 1,016.00            | \$ 1,016.00        |
| 5                           | REAR LIGHT REFLECTOR - LH / RH          | 2   | \$ 82.00               |                    |
| 6                           | REAR BUMPER REINFORCMENT BEAM           | 1   | \$ 940.00              |                    |
| 7                           | REAR BUMPER SEAL                        | 2   | \$ 28.00               |                    |
| 8                           | REAR BUMPER GUIDE SECTION - LH / RH     | 2   | \$ 46.00               |                    |
| 9                           | REAR PARKING AID SENSOR - INNER / OUTER | 2   | TBC                    |                    |
| 10                          | REAR PARKING AID SENSOR SEAL RING       | 4   | \$ 14.00               |                    |
| 11                          | SUNDRIES                                |     | \$ 200.00              |                    |
| <b>TOTAL SPARE PARTS</b>    |                                         |     | <b>\$ 5,218.00</b>     | <b>\$ 3,742.50</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                         |     | <b>\$ 2,752.00</b>     | <b>\$ 2,152.00</b> |
| <b>GRAND TOTAL</b>          |                                         |     | <b>\$ 7,970.00</b>     | <b>\$ 5,894.50</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT