



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

MS FIRST CAPITAL INSURANCE LTD

INV No. AC2200154

36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877

INV Date 07/01/2022
Reference CC4/FCI21013261/R1pa3q2
Code FCI2

PROFESSIONAL SERVICE FEE

Vehicle No. SJH 699Z
Insured Veh. YN 3186H
Claim No. D21003541MFCV/PTE/KT
Policy No.
Accident Date 27/12/2021
Inspection Date 29/12/2021

Description	Total
Survey Inspection	236.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	236.00
GST (7%)	16.52
Grand Total	252.52

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CC4/FCI21013261/R1pa3q2	
			Date: 07/01/2022	
			Code: FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 3186H	Veh. Inspected	SJH 699Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	D21003541MFCV/PTE/KT	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	28/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES BENZ GLA180 URBAN E	c.c	1595	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WDC1569422J659991	Colour	WHITE	
Odometer	19936 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/50 R18	CONTINENTAL	6 mm	
L/H Front Tyre	235/50 R18	CONTINENTAL	6 mm	
R/H Rear Tyre	235/50 R18	CONTINENTAL	6 mm	
L/H Rear Tyre	235/50 R18	CONTINENTAL	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	27/12/2021	Inspection Date	29/12/2021	
Survey held at	48 TOH GUAN RD EAST #02-146			
Repairer	AUTOMOTIVE REPAIR CENTRE PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			2 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 699Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	SIDE MIRROR RH COVER (100)	MISSING	240.00	240.00
1	SIDE MIRROR RH BASE (80)	CRACKED	88.00	88.00
1	SIDE MIRROR RH ASSY (10)	MISSING	520.00	520.00
1	SIDE MIRROR RH MIRROR (40)	MISSING	168.00	168.00
	LESS 10% DISCOUNT		-	-101.60
			1,016.00	914.40
	<u>LABOUR</u>			
	REPAIR ,REFIT ,REMOVE AND REPLACE AFFECTED ACCIDENT PARTS.		500.00	100.00
	REPAIR FRONT BONNET .	NOT NECESSARY	250.00	-
	SPRAY PAINTING (SIDE MIRROR & FRONT BONNET).		400.00	300.00
	DIAGNOSE AND RECTIFY SIDE MIRROR FAULT CODES.		250.00	100.00
	CHECK AND RECTIFY WIRING ,INCL ,ADJUST FOCUS AREA OF HEADLAMP.		35.00	35.00
			1,435.00	535.00
	GRAND TOTAL		2,451.00	1,449.40
RECOMMENDED COST OF REPAIRS				1,449.40

Report Ref No. CC4/FCI21013261/R1pa3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd


51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 699Z

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SJH 699Z

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

