

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

Estimate

ESTIMATE NO. : EST2112-326-TG

DATE : 27-Dec-2021

POLICY NO. : Auto & Gen P10613013R00

VEHICLE REG. NO. : SJH699Z

VEHICLE MAKE : MERCEDES / GLA180 URBAN

TO Motor Claim Department
First Capital Insurance Limited
 36 Robinson Road #16-01 City House
 Singapore 068877
 Tel: 6507 3848, Fax: 65073849

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Side Mirror RH Cover (100)	1	\$ 240.00	\$ 240.00
2	Side Mirror RH Base (80)	1	\$ 88.00	\$ 88.00
3	Side Mirror RH Assy (10)	1	\$ 520.00	\$ 520.00
4	Side Mirror RH Mirror (40)	1	\$ 168.00	\$ 168.00
Total Spare Parts				\$ 1,016.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
5	Repair, Refit, Remove and Replace Affected Accident Parts	1	\$ 500.00	\$ 500.00
6	Repair Front Bonnet	1	\$ 250.00	\$ 250.00
7	Spray painting (Side Mirror & Front Bonnet)	1	\$ 400.00	\$ 400.00
8	Diagnose and Rectify Side Mirror Fault Codes	1	\$ 250.00	\$ 250.00
9	Check and rectify wiring, incl. adjust focus area of headlamp	1	\$ 35.00	\$ 35.00
Total Labour				\$ 1,435.00
Amount Before Excess				\$ 2,451.00
Add GST @ 7%				171.57
Total Amount Payable				\$ 2,622.57

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts