

38 Woodlands Industrial Park E1  
 #05-18, Singapore 757700  
 Tel: 64688834 Fax: 64622278  
 E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2112-326-TG  
 DATE : 27-Dec-2021  
 POLICY NO. : Auto & Gen P10613013R00  
 VEHICLE REG. NO. : SJH699Z  
 VEHICLE MAKE : MERCEDES / GLA180 URBAN

TO Motor Claim Department  
 First Capital Insurance Limited  
 36 Robinson Road #16-01 City House  
 Singapore 068877  
 Tel: 6507 3848, Fax: 65073849

FOR SURVEYOR

**ESTIMATE REPAIR COST**

| NO.                         | DESCRIPTION   | QUANTITY | UNIT COST | TOTAL COST           |
|-----------------------------|---|----------|-----------|----------------------|
| <b>SPARE PARTS</b>          |   |          |           |                      |
| 1                           | Side Mirror RH Cover (100) <i>MIS /</i>                       | 1        | \$ 240.00 | \$ 240.00            |
| 2                           | Side Mirror RH Base (80) <i>CM /</i>                          | 1        | \$ 88.00  | \$ 88.00             |
| 3                           | Side Mirror RH Assy (10) <i>MIS /</i>                         | 1        | \$ 520.00 | \$ 520.00            |
| 4                           | Side Mirror RH Mirror (40) <i>MIS /</i>                       | 1        | \$ 168.00 | \$ 168.00            |
| <b>Total Spare Parts</b>    |   |          |           | \$ 1,016.00          |
| <b>SPECIAL NETT</b>         |   |          |           |                      |
| <b>Total Special Nett</b>   |   |          |           | \$ -                 |
| <b>LABOUR</b>               |   |          |           |                      |
| 5                           | Repair, Refit, Remove and Replace Affected Accident Parts     | 1        | \$ 500.00 | <del>\$ 500.00</del> |
| 6                           | Repair Front Bonnet   | 1        | \$ 250.00 | <del>\$ 250.00</del> |
| 7                           | Spray painting (Side Mirror & Front Bonnet)                   | 1        | \$ 400.00 | <del>\$ 400.00</del> |
| 8                           | Diagnose and Rectify Side Mirror Fault Codes                  | 1        | \$ 250.00 | <del>\$ 250.00</del> |
| 9                           | Check and rectify wiring, incl. adjust focus area of headlamp | 1        | \$ 35.00  | \$ 35.00             |
| <b>Total Labour</b>         |   |          |           | \$ 1,435.00          |
| <b>Amount Before Excess</b> |   |          |           | \$ 2,451.00          |
| <b>Add GST @ 7%</b>         |   |          |           | 171.57               |
| <b>Total Amount Payable</b> |   |          |           | \$ 2,622.57          |

1016  
102  
914.40

535

Estimate prepared by: KenGuan  
 The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

914.40  
535.00  
1449.40

*Rasul*  
 Hp 90010068  
 2 days  
 29/12/21 @ 16/0  
 P/P  
 Resy before paint