



CLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /Mr Kamaruddin Bin Md Sahabudin Reg No/Reg Date SMQ5987B / 26/11/201 Date In/Mileage / 206759 Chassis No MMBSTA13AKH002532 Engine No 3A92UHX6365 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	28/12/2021/ 18:01	BLE	261 / Edwin Caina	19394			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								3150.00
RENEW FR BUMPER , FR SUPPORT , BONNET , LHF FENDER & RHF FENDER @450 X 4								1800
REPAIR LHF A PILLAR , RHF A PILLAR & RHF DOOR								2450
E PNT98000								2800.00
RESPRAY FR BUMPER , FR SUPPORT , BONNET , LHF FENDER , RHF FENDER @350 X 7								
LHF A PILLAR , RHF A PILLAR & RHF DOOR								
E PNT88000								100.00
REMOVE & REFIT AC COND & RADIATOR								80.00
M SUNDRY								30.00
TOP UP AC GAS								120.00
A 54900099								50.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP ATM								80.00
A 10028901								20.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
M SUNDRY								
SUPPLY FR NUMBER PLATE WITH CASING								
M SUNDRY								
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								
SUPPLY BODY PNL SEALANT								
M SUNDRY								
Sundries								
M FACE,FR BUMPER					1.00	706.00	23.00	543.62
M CLIP,FR BUMPER					5.00	4.00	23.00	15.40
M COVER,HEADLAMP SUPT PANEL					1.00	62.00	23.00	47.74
M BRACKET,FR BUMPER,LH					1.00	13.00	23.00	10.01
M BRACKET,FR BUMPER,RH					1.00	13.00	23.00	10.01
M GRILLE,FR UNDER					1.00	165.00	23.00	127.05
M GARNISH,FR BUMPER,LH					1.00	127.00	23.00	97.79
M GARNISH,FR BUMPER,RH					1.00	127.00	23.00	97.79
M TOW COVER,FR BUMPER					1.00	12.00	23.00	9.24
M MARK,THREE-DIAM					1.00	70.00	23.00	53.90
M GRILLE,RADIATOR					1.00	557.00	23.00	428.89

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	<table> <tr> <td>Cust No/Name</td><td>/Mr Kamaruddin Bin Md Sahabudin</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMQ5987B / 26/11/201</td></tr> <tr> <td>Date In/Mileage</td><td>/ 206759</td></tr> <tr> <td>Chassis No</td><td>MMBSTA13AKH002532</td></tr> <tr> <td>Engine No</td><td>3A92UHX6365</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>P57 WINE RED PEARL / BK BLACK</td></tr> </table>	Cust No/Name	/Mr Kamaruddin Bin Md Sahabudin	Reg No/Reg Date	SMQ5987B / 26/11/201	Date In/Mileage	/ 206759	Chassis No	MMBSTA13AKH002532	Engine No	3A92UHX6365	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	P57 WINE RED PEARL / BK BLACK
Cust No/Name	/Mr Kamaruddin Bin Md Sahabudin														
Reg No/Reg Date	SMQ5987B / 26/11/201														
Date In/Mileage	/ 206759														
Chassis No	MMBSTA13AKH002532														
Engine No	3A92UHX6365														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	P57 WINE RED PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2021/ 18:01	BLE	261 / Edwin Caina	19394

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M HOOD <i>bum</i>	1.00	737.00	23.00	567.49
M HINGE, HOOD, LH <i>? Xan</i>	1.00	56.00	23.00	43.12
M HINGE, HOOD, RH <i>st</i>	1.00	56.00	23.00	43.12
M INSULATOR, HOOD <i>de</i>	1.00	177.00	23.00	136.29
M CLIP, HOOD INSULATOR <i>me</i>	6.00	3.00	23.00	13.86
M LATCH, HOOD <i>st</i>	1.00	69.00	23.00	53.13
M FENDER, FR LH <i>repair</i>	1.00	500.00	23.00	385.00
M FENDER, FR RH <i>buc</i>	1.00	500.00	23.00	385.00
M SHIELD, FR WHEELHOUSE, LH <i>Xan</i>	1.00	98.00	23.00	75.46
M SHIELD, FR WHEELHOUSE, RH <i>? Xan</i>	1.00	98.00	23.00	75.46
M CLIP, INNER SHIELD <i>na</i>	1.00	4.00	23.00	36.96
M PANEL ASSY, FR END <i>? bt</i>	1.00	1055.00	23.00	812.35
M PANEL, HEADLAMP SUPPORT, UPR <i>? bt</i>	1.00	66.00	23.00	50.82
M HEADLAMP ASSY, LH <i>ca</i>	1.00	663.00	23.00	510.51
M HEADLAMP ASSY, RH <i>ca</i>	1.00	663.00	23.00	510.51
M LAMP ASSY, FOG, FR LH <i>? Xan</i>	1.00	305.00	23.00	234.85
M LAMP ASSY, FOG, FR RH <i>? Xan</i>	1.00	305.00	23.00	234.85
M GARNISH, FR PILLAR, LH <i>? Xan</i>	1.00	30.00	23.00	23.10
M GARNISH, FR PILLAR, RH <i>? Xan</i>	1.00	30.00	23.00	23.10
M GARNISH, FR FENDER <i>? Xan</i>	1.00	65.00	23.00	100.10
M CONDENSER ASSY, A/C REFRIGE <i>? bt</i>	1.00	762.00	23.00	586.74
M PANEL, AIR GUIDE <i>ca</i>	1.00	112.00	23.00	86.24
M RADIATOR ASSY <i>? st</i>	1.00	972.00	23.00	748.44
M FAN, COOLING <i>? ca</i>	1.00	77.00	23.00	59.29
M SHROUD, COOLING FAN <i>? short</i>	1.00	131.00	23.00	100.87
M MOTOR, COOLING FAN <i>? short</i>	1.00	484.00	23.00	372.68
M TANK, WINDSHIELD WASHER <i>- dev</i>	1.00	75.00	23.00	57.75
M EMBLEM ECO <i>ca</i>	2.00	17.00	00.00	34.00
M LLC 4L <i>ca</i>	1.00	26.00	23.00	20.02

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: *Rasul - Hy 90010068*SURVEYOR SIGNATURE: *R*

Confirm & accepted by

DATE: *29/12/21 @ 1140*REMARKS: *8 days**REVERT/EXCESS: TBA*

7% GST on

Nett

14,332.55

1003.28

Total Payable

15,335.83

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.