



AIG-OD (REVERT)  
SURVEY: 29/12/21  
LKK-PASUL

VEHICLE NO : SMP2230 B

MODEL : MIT/ATRAGE 1.2 CVT

WIP : 17724

Material	: \$	<u>4,079.28</u>
Labour	: \$	<u>5,330.00</u>
Sub-Total	: \$	<u>9,409.28</u>
Less 2% Disc	: \$	<u>—</u>
Less Excess	: \$	<u>—</u>
Total	: \$	<u>9,409.28</u>
GST 7%	: \$	<u>658.65</u>
Grand Total	: \$	<u>10,067.93</u>
Finalise By/Date :		<u>Wahy on 11/04/22</u>

REVERT BACK WITHIN 7 DAYS,  
OTHERWISE WILL PROCEED WITH INVOICING

SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 10 WORKING DAYS + 4 days (2 wk. ends)

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/12/2021	Cust No/Name /Mr Ho Choon Sing (he Junxing) Reg No/Reg Date SMP2230B / 17/09/2019 Date In/Mileage 29/12/2021/ 46169 Chassis/Package MMBSTA13AKH002502 /# Engine No 3A92UHX6019 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim P01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	11/04/2022/ 16:15	TLE	884 / Lauro Songcuan	17724			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000				RENEW LH REAR FENDER, REAR BUMPER, REAR END PANEL & BOOTLID				2250.00 ✓
E PNT98000				SPRAY PAINT REAR BUMPER, REAR BUMPER BODY KIT, REAR END PANEL, BOOTLID, LH REAR FENDER & RH REAR FENDER				1925.00 ✓
E PNT88000				REMOVE & REFIT BOOTLID COMPONENTS				120.00 ✓
E PNT88000				REMOVE & REFIT REAR FLOOR BOARD, TRIM, CARPET & SEAT				120.00 ✓
A 13900099				REMOVE & REFIT FUEL TANK ASSY				225.00 ✓
A 54900099				CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				30.00 ✓
A 10028901				TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00 ✓
E PNT88000				REMOVE & REFIT REAR WINDSCREEN GLASS				240.00 ✓
M SUNDRY				SUPPLY REAR WINDSCREEN SEALANT				80.00 ✓
E PNT88000				REMOVE & REFIT REVERSE SENSOR				80.00 ✓
M SUNDRY				APPLY ANTI CORROSION ON AFFECTED AREAS				40.00 ✓
M SUNDRY				SUPPLY BODY PANEL SEALANT				40.00 ✓
M SUNDRY				SUPPLY C&C BADGE				40.00 ✓
M SUNDRY				SUNDRIES				20.00 ✓
X				FACE,RR BUMPER ✓	1.00	751.00	23.00	578.27 ✓
X				BRACKET,RR BUMPER,LH ?	1.00	28.00	23.00	21.56 ?
X				CLIP,RR BUMPER ✓	4.00	4.00	23.00	12.32 ✓
X				PANEL,QTR,OTR LH ✓	1.00	759.00	23.00	584.43 ✓

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.

**PRO-FORMA INVOICE**

Co Reg No : 197701469G

**THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 29/12/2021	Cust No/Name /Mr Ho Choon Sing (he Junxing)
	Reg No/Reg Date SMP2230B / 17/09/2019
	Date In/Mileage 29/12/2021/ 46169
	Chassis/Package MMBSTA13AKH002502 /#
	Engine No 3A92UHX6019
	Make/Model MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim P01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	11/04/2022/ 16:15	TLE	884 / Lauro Songcuan	17724
Description of Goods / Services					
		Qty	Unit Price	Disc%	Amount
X	PANEL,RR COMB LAMP HSG,LH ?	1.00	60.00	23.00	46.20 ?
X	PANEL,RR END ✓	1.00	427.00	23.00	328.79 ✓
X	MUD GUARD,RR LH x?	1.00	41.00	23.00	31.57 ?
X	STOPPER,WINDSHIELD GLASS ✓	2.00	3.00	23.00	4.62 ✓
X	SPACER,RR WINDOW ✓	3.00	9.00	23.00	20.79 ✓
X	PANEL,TRUNK LID ✓	1.00	795.00	23.00	612.15 ✓
X	MARK,THREE-DIA ✓	1.00	70.00	23.00	53.90 ✓
X	MARK,ATTRAGE ✓	1.00	21.00	23.00	16.17 ✓
X	UNPAINTED BODYKITS ✓	1.00	1643.00	00.00	1643.00 ✓
X	DECAL,MIVEC ✓	1.00	36.00	23.00	27.72 ✓
X	CLIP,RR END TRIM	4.00	3.00	23.00	9.24 X
X	GROMMET,RR END TRIM	4.00	3.00	23.00	9.24 X
X	GROMMET,TAIL LAMP	2.00	3.00	23.00	4.62 X
X	GROMMET,TAIL LAMP	1.00	3.00	23.00	2.31 X
X	CAP,TAIL LAMP	1.00	3.00	23.00	2.31 X
X	BUZZER,KEYLESS OPERATIO,RR	1.00	91.00	23.00	70.07 X
Z	TEXT				
	AIG OD CLAIM - REVERT				
	SURVEY: RASUL (LKK) 29/12/2021				
	DOA: 19/11/2021				
	10 DAYS				
<i>Guarantee Your Warranty, Maintain with Cycle &amp; Carriage!</i>					

Parts	4,079.28	Nett	9,409.28
Labour	5,110.00	7% GST on	658.65
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00		
Sundry/Others	220.00		
Total(w/o GST)	9,409.28	<b>Total Payable</b>	<b>10,067.93</b>

This is not an official tax invoice.  
 This is a computer generated document, no signature is required.



CYCLE & CARRIAGE

INSURANCE CO. : **AIG**

Supplementary For Registration No.: **SMP 2230 B**

		<b><u>Cost (\$)</u></b>
<b><u>Materials</u></b>		
1	Clip, RR End Trim (4 pcs)	12.00
2	Grommet, RR End Trim (4 pcs)	12.00
3	Grommet, Tail Lamp (2 pcs)	6.00
4	Grommet, Tail Lamp (2 pcs)	3.00
5	Cap, Tail Lamp	3.00
6	Buzzer, Keyless Operation, RR	91.00
		<u>127.00</u>
20% Discount		<u>29.21</u>
		97.79
7% Gst		6.85
<b>Total</b>		<b><u>104.64</u></b>

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD

LARRY SONGCUAN  
CUSTOMER SERVICE  
TEL: 6568 4658  
FAX : 6567 5258

CAR NO: SMP2230B

WIP: 17724

(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	<del>Extension</del> Panel, MR BUZZER	? / SUPP			<del>5301F995</del>
2	UH Panel, RR Combination Lamp Housing	? / SUPP			5301F995
3	Clip, MR End Trim	? / SUPP			7259A2208A 4pcs
4	Grommet 4pcs	? / SUPP			7259A221 4pcs
5	Ground, Tailamp 2pcs	? / SUPP			MU 000283 2pcs
6	Ground, Tailamp 1pc	? / SUPP			MU 000368 1pc
7	Clip, Tailamp 1pc	? / SUPP			MR 482761 1pc
8	Bracket, RR Buzzer UH	? / SUPP			6410C433 1pc
9	Mod ground, RR UH	? / SUPP			5370B565
10	BUZZER	? / SUPP			4637A126.
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

	DATE	TAKEN BY
PHOTO BEFORE PAINT	12/1	W. Venter
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBOARD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: ATRAAGE  
 SURVEYOR: RASUL

All DTCS

For use: SMP 2230 B  
 Before use: MTFSA not to check all  
 is SOS found

2022.01.25

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCS	
AT/CVT/A-MTTC-SST	KOSOSS_99880010		No DTCS	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCS	
ABS/ASC/ASTC/WSS	KOSOSS_99880010		No DTCS	
SRS-AIR BAG	KOSOSS_99880010		No DTCS	
Air Conditioner	KOSOSS_99880010		No DTCS	
ETACS	KOSOSS_99880010	B1707	Flasher open	Active
Meter	KOSOSS_99880010		No DTCS	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCS	

All DTCS

*Re: was SMP 2220 B  
 Double very M/T-3x VCS unit to Base all  
 See Board  
 15 Jan 2022*

System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name	Malfunction Condition
MPI/GDI/DIESEL	KOSOSS_99880010		No DTCS	
AT/CVT/A-MT/T-C-SST	KOSOSS_99880010		No DTCS	
4WS/Electric Power Steering	KOSOSS_99880010		No DTCS	
ABS/ASC/ASTC/MSS	KOSOSS_99880010		No DTCS	
SRS-AIR BAG	KOSOSS_99880010		No DTCS	
Air Conditioner	KOSOSS_99880010		No DTCS	
ETACS	KOSOSS_99880010		No DTCS	
Meter	KOSOSS_99880010		No DTCS	
Steering Angle Sensor	KOSOSS_99880010		Non-target System	
KOS/OSS/IMMO/Keyless (with KOS)	KOSOSS_99880010		No DTCS	