



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Mr Ho Choon Sing (he Junxing)
	Reg No/Reg Date	SMP2230B / 17/09/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AKH002502
	Engine No	3A92UHX6019
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2021/ 11:21	TLE	261 / Edwin Caina	17724

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW LHR FENDER , RR BUMPER , RR END PNL & BOOTLID REPAIR RR FLR PNL	@450 X 5			2250 / 3800.00
E PNT98000 RESPRAY RR BUMPER , RR BUMPER BODY KIT , RR END PNL , RR FLR PNL , BOOTLID , LHR FENDER & RHR FENDER	@350 X 5.5			1925 / 3850.00
E PNT88000 REMOVE & REFIT BOOTLID COMPONENT				120.00
E PNT88000 REMOVE & REFIT RR FLR BOARD , TRIM , CAREPET & SEAT				120.00
A 13900099 REMOVE & REFIT FUEL TANK ASSY				225 / 300.00
A 54900099 CHECK WIRING ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM				120.00
E PNT88000 REMOVE & REFIT RR WINDSCREEN GLASS				240 / 300.00
M SUNDRY SUPPLY WINDSCREEN SEALANT				80.00
M SUNDRY SUPPLY RR NUMBER PLATE WITH CASING				X 80.00
E PNT88000 REMOVE & REFIT REVERSE SENSOR				80 / 100.00
M SUNDRY SUPPLY REVERSE SENSOR				? 220.00
M SUNDRY APPLY ANTI CORROSION ON AFFECTED AREAS				40 / 80.00
M SUNDRY SUPPLY BODY PNL SEALANT				40 / 80.00
M SUNDRY SUPPLY C&C BADGE				40 / 50.00
M SUNDRY				20 / 80.00

Estimate

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



MITSUBISHI  
MOTORS

Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name	/Mr Ho Choon Sing (he Junxing)
	Reg No/Reg Date	SMP2230B / 17/09/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AKH002502
	Engine No	3A92UHX6019
	Make/Model	MIT/19MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	28/12/2021/ 11:21	TLE	261 / Edwin Caina	17724

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
Sundries				
M FACE,RR BUMPER <i>cmf</i>	1.00	751.00	23.00	578.27
M BRACKET,RR BUMPER,LH	1.00	28.00	23.00	21.56
M BRACKET,RR BUMPER,RH	1.00	28.00	23.00	21.56
M CLIP,RR BUMPER <i>re</i>	4.00	4.00	23.00	12.32
M PANEL,QTR,OTR LH <i>bu</i>	1.00	759.00	23.00	584.43
M PANEL,RR COMB LAMP HSG,LH	1.00	60.00	23.00	46.20
M EXTN,QTR PANEL,UPR OTR LH	1.00	118.00	23.00	90.86
M PANEL,RR END <i>bt</i>	1.00	427.00	23.00	328.79
M MUD GUARD,RR LH <i>pho</i>	1.00	41.00	23.00	31.57
M SHIELD,RR WHEELHOUSE,LH	1.00	40.00	23.00	30.80
M STOPPER,WINDSHIELD GLASS <i>re</i>	1.00	3.00	23.00	4.62
M SPACER,RR WINDOW <i>re</i>	3.00	9.00	23.00	20.79
M PANEL,TRUNK LID <i>bt</i>	1.00	795.00	23.00	612.15
M WEATHERSTRIP,TRUNK LID	1.00	157.00	23.00	120.89
M HINGE,TRUNK LID,LH	1.00	203.00	23.00	156.31
M HINGE,TRUNK LID,RH	1.00	203.00	23.00	156.31
M LATCH,TRUNK LID	1.00	218.00	23.00	167.86
M STRIKER,TRUNK LID LATCH	1.00	20.00	23.00	15.40
M MARK,THREE-DIA <i>re</i>	1.00	70.00	23.00	53.90
M MARK,ATTRAGE <i>re</i>	1.00	21.00	23.00	16.17
M REFLECTOR LH	1.00	23.00	23.00	17.71
M LAMP ASSY,COMB,RR LH	1.00	337.00	23.00	259.49
M UNPAINTED BODYKITS <i>cmf</i>	1.00	1643.00	20.00	1314.40
M DECAL,MIVEC <i>re</i>	1.00	36.00	23.00	27.72

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

SURVEYOR NAME: Rajan - Hp 90010068  
 SURVEYOR SIGNATURE: [Signature]  
 DATE: 29/12/21 @ 1210  
 REMARKS: 10 days

Confirm & accepted by

Rajan/Excess: TBA  
Resy before paint

	Nett	14,100.08
7% GST on	14100.08	987.01
<b>Total Payable</b>		<b>15,087.09</b>

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.