



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722 ON BEHALF OF GOH ZHI HAO MICHAEL VANDOL			Ref: CS/TP21013266/Kqce2 Date: 05/01/2022 Code: TP393	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.		Veh. Inspected	SLB 555M
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	30/11/2021
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ C 180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2012
	Chassis No.	WDD2040312A770073	Colour	WHITE
	Odometer	193892 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/35Z R19	MICHELIN	7 mm
	L/H Front Tyre	225/35Z R19	MICHELIN	7 mm
	R/H Rear Tyre	235/35Z R19	MICHELIN	6 mm
	L/H Rear Tyre	235/35Z R19	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/11/2021	Inspection Date	30/11/2021
	Survey held at	RC AUTO 160 SIN MING DRIVE #06-20 SIN MING AUTOCITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	