

Shiau Chan (LKKAUTO)

From: Simon Ho (LKKAUTO)
Sent: Monday, 3 January 2022 5:01 PM
To: Shiau Chan (LKKAUTO)
Subject: RE: INDEPENDENT-TP SLB 555M SURVEYED BY KENNETH (OUR REF: CS/TP21013266/Kqc)

Dear Shiau Chan,

AUDIT CHECK DONE FOR SLB555M, FOUND HEADREST NOT REQUIRED TO REPLACE, REPLACE REPAIR KIT WILL DO & NET VALUE MUST WORK OUT FOR SUCH REPAIR AMOUNT.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Shiau Chan (LKKAUTO)
Sent: Monday, 3 January, 2022 4:36 PM
To: Simon Ho (LKKAUTO)
Subject: INDEPENDENT-TP SLB 555M SURVEYED BY KENNETH (OUR REF: CS/TP21013266/Kqc)

Dear Simon,

For your audit.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)