

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1054/2021/JT
DATE : 24-Dec-21
WIP : 60201

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

15-Feb-22

OWNER'S NAME : MR JIANG HUI
ADDRESS : 25 YIO CHU KANG DRIVE
SINGAPORE 786291
TELEPHONE : HP +65 98245904
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100237541-11
VEHICLE NO : **SJZ 3770 K**
MODEL CODE : AUDI A6 2.0 TFSI
MODEL YEAR : 19/11/2010
ENGINE NO : BPJ200482
CHASSIS NO : WAUZZZ4F6AN073939
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Dec-21
PLACE OF ACCIDENT : ANG MO KIO AVE 3

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 3770 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		: \$	4,552.00	\$	2,402.00

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 3770 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,506.00	\$	2,004.80
2	FRONT BUMPER SIDE REINFORCEMENT	1	\$ 892.00		
3	FRONT BUMPER BRACKET - LH / RH	2	\$ 482.00		
4	FRONT BUMPER DISTANCE PIECE - LH & RH	2	\$ 27.00		
5	FRONT BUMPER COMPENSATING PIECE	2	\$ 46.00		
6	FRONT BUMPER COVER BRACKET - LH / RH UPPER	2	\$ 70.00	\$	27.28
7	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 106.00		
8	FRONT BUMPER PULL STRAP - LOWER CENTER	4	\$ 138.00		
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 236.00		
10	FRONT BUMPER LICENCE PLATE TRIM	1	\$ 195.00	\$	156.00
11	FRONT BUMPER TRIM STRIP - LH / RH	2	\$ 618.00		
12	FRONT BUMPER GRILLE COVER	1	\$ 113.00		
13	CAUTION STICKER	1	\$ 14.00		
14	AIR COND STICKER	1	\$ 30.00		
15	RADIATOR GRILLE	1	\$ 816.00	\$	652.40
16	HEADLIGHT - RH	1	\$ 3,252.00	\$	2,601.60
17	FOG LAMP - RH	1	\$ 364.00		
18	LIFT CYLINDER NOZZLE CARRIER - RH	1	\$ 274.00		
19	LIFT CYLINDER HOSE	5	\$ 191.00		
20	FRONT NO PLATE	S/N	\$ 60.00	\$	60.00
21	SUNDRIES		\$ 250.00		
TOTAL SPARE PARTS		:	\$ 10,680.00	\$	5,502.08
TOTAL LABOUR CHARGES		:	\$ 4,552.00	\$	2,402.00
GRAND TOTAL		:	\$ 15,232.00	\$	7,904.08

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 bl-12/02/22

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT