



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1054/2021/JT
DATE : 24-Dec-21
WIP : 60201

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

4 days - ok - Johnny Boo

15-Feb-22

OWNER'S NAME : MR JIANG HUI
ADDRESS : 25 YIO CHU KANG DRIVE
SINGAPORE 786291
TELEPHONE : HP +65 98245904
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100237541-11
VEHICLE NO : **SJZ 3770 K**
MODEL CODE : AUDI A6 2.0 TFSI
MODEL YEAR : 19/11/2010
ENGINE NO : BPJ200482
CHASSIS NO : WAUZZZ4F6AN073939
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Dec-21
PLACE OF ACCIDENT : ANG MO KIO AVE 3

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJZ 3770 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$	360.00	\$	360.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$	500.00
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$	2,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
6	SUPPLEMENTARY			\$	780.00
TOTAL LABOUR CHARGES		:	\$ 4,552.00	\$	3,182.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 3770 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,506.00	\$ 2,004.80
2	FRONT BUMPER SIDE REINFORCEMENT	1	\$ 892.00	
3	FRONT BUMPER BRACKET - LH / RH	2	\$ 482.00	
4	FRONT BUMPER DISTANCE PIECE - LH & RH	2	\$ 27.00	
5	FRONT BUMPER COMPENSATING PIECE	2	\$ 46.00	
6	FRONT BUMPER COVER BRACKET - LH / RH UPPER	2	\$ 70.00	\$ 27.28
7	FRONT BUMPER GUIDE SECTION - LH / RH	2	\$ 106.00	
8	FRONT BUMPER PULL STRAP - LOWER CENTER	4	\$ 138.00	
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH	2	\$ 236.00	
10	FRONT BUMPER LICENCE PLATE TRIM	1	\$ 195.00	\$ 156.00
11	FRONT BUMPER TRIM STRIP - LH / RH	2	\$ 618.00	
12	FRONT BUMPER GRILLE COVER	1	\$ 113.00	
13	CAUTION STICKER	1	\$ 14.00	
14	AIR COND STICKER	1	\$ 30.00	
15	RADIATOR GRILLE	1	\$ 816.00	\$ 652.40
16	HEADLIGHT - RH	1	\$ 3,252.00	\$ 2,601.60
17	FOG LAMP - RH	1	\$ 364.00	
18	LIFT CYLINDER NOZZLE CARRIER - RH	1	\$ 274.00	
19	LIFT CYLINDER HOSE	5	\$ 191.00	
20	FRONT NO PLATE	S/N	\$ 60.00	\$ 60.00
21	SUNDRIES		\$ 250.00	
22	Supplementary			868.8
TOTAL SPARE PARTS		:	\$ 10,680.00	\$ 6,370.88
TOTAL LABOUR CHARGES		:	\$ 4,552.00	\$ 3,182.00
GRAND TOTAL		:	\$ 15,232.00	\$ 9,552.88

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bi-12/02/22



Supplementary Estimate

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 / Fax: 6256 4315

Estimate No.

PA/OD/1054/2021/JT

Date

3-Mar-22

Service Advisor

GLORY

Pages

1 of 1

Regn No

SJZ 3770 K

Model No

AUDI A6 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Labours</u>			
1	TO REMOVE AND RENEW AIRCON CONDENSER. TO CARRY OUT PRESSURISE, VACUUM AND REGAS.	S/N \$ 780.00	\$ 780.00
<u>Parts</u>			
1	AIRCON CONDENSER	\$ 829.00	\$ 662.80
2	VALVE	\$ 52.00	\$ 41.60
3	PRESSURE SENDER	\$ 206.00	\$ 164.40
GRAND TOTAL		\$ 1,867.00	\$ 868.80

For Premium Automobiles Pte Ltd

 Authorised Signature