

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1054/2021/JT
DATE : 24-Dec-21
WTP : 60201

Veron.

\$ 7904.80

0.4 Days.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 5880 4602 - Fax: 6880 4838

OWNER'S NAME : MR JIANG HUI
ADDRESS : 25 YIO CHU KANG DRIVE
SINGAPORE 786291
TELEPHONE : HP +65 98245904
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2100237541-11
VEHICLE NO : SJZ 3770 K
MODEL CODE : AUDI A6 2.0 TFSI
MODEL YEAR : 19/11/2010
ENGINE NO : BPJ200482
CHASSIS NO : WAUZZZ4F6AN073939
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Dec-21
PLACE OF ACCIDENT : ANG MO KIO AVE 3



55 UBI ROAD 1, SINGAPORE 408699

TEL 6366 2323 FAX 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE S1Z 3770 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N \$ 360.00	✓ ✓
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00	250 ✓
3	TO DISMANTLE AND RENEW FRONT BUMPER AND RHS HEADLIGHT. TO REPAIR BONNET. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,600.00	500 ✓
4	TO RESPRAY FRONT BUMPER AND BONNET.	\$ 2,000.00	1100 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		\$ 4,552.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1 SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NOPA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SJZ 3770 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Delud</i>	1	\$ 2,506.00	✓ 2004.80
2	FRONT BUMPER SIDE REINFORCEMENT <i>Not new</i>	1	\$ 892.00	? X
3	FRONT BUMPER BRACKET - LH / RH <i>Not new</i>	2	\$ 482.00	+ X
4	FRONT BUMPER DISTANCE PIECE - LH & RH <i>Not new</i>	2	\$ 27.00	+ X
5	FRONT BUMPER COMPENSATING PIECE <i>Not new</i>	2	\$ 46.00	+ X
6	FRONT BUMPER COVER BRACKET - LH / RH UPPER <i>Not new</i>	2	\$ 70.00	? 27.28
7	FRONT BUMPER GUIDE SECTION - LH / RH <i>Not new</i>	2	\$ 106.00	+ X
8	FRONT BUMPER PULL STRAP - LOWER CENTER <i>Not new</i>	4	\$ 138.00	+ X
9	FRONT BUMPER AIR GUIDE GRILLE - LH / RH <i>Not new</i>	2	\$ 236.00	+ X
10	FRONT BUMPER LICENCE PLATE TRIM <i>Delud</i>	1	\$ 195.00	✓ 156.00
11	FRONT BUMPER TRIM STRIP - LH / RH <i>Not new</i>	2	\$ 618.00	+ X
12	FRONT BUMPER GRILLE COVER <i>Not new</i>	1	\$ 113.00	? X
13	CAUTION STICKER <i>Not new</i>	1	\$ 14.00	? X
14	AIR COND STICKER <i>Not new</i>	1	\$ 30.00	? X
15	RADIATOR GRILLE <i>Not new</i>	1	\$ 816.00	✓ 652.40
16	HEADLIGHT - RH <i>Not new</i>	1	\$ 3,252.00	✓ 2601.60
17	FOG LAMP - RH <i>Not new</i>	1	\$ 364.00	+ X
18	LIFT CYLINDER NOZZLE CARRIER - RH <i>Not new</i>	1	\$ 274.00	+ X
19	LIFT CYLINDER HOSE <i>Not new</i>	5	\$ 191.00	+ X
20	FRONT NO PLATE <i>Not new</i>	S/N	\$ 60.00	✓ 60
21	SUNDRIES <i>Not new</i>		\$ 250.00	? X

TOTAL SPARE PARTS : \$ 10,680.00

TOTAL LABOUR CHARGES : \$ 4,552.00

GRAND TOTAL : \$ 15,232.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME
SURVEYED DATE
AUTHORISED DATE
EXCESS COST
LIABILITY
REMARKS

:
:
:
:
:
:

Adrian King.
28/12/21

Not Authorised, 04 Days
llg.

PLEASE NOTE

:

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Complementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: