



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1050/2021/JT
DATE : 23-Dec-21
WIP : 60074

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

3 days - ok - Jy - 29 Jan 22

OWNER'S NAME : MR JOHN YEOG YING JUN (JONG YANG YINGJUN)
ADDRESS : 1 ALEXANDRA VIEW
#30-02
SINGAPORE 158748
TELEPHONE : HP +65 81331420
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800064094-03
VEHICLE NO : SMA 3702 D
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 04/06/2018
ENGINE NO : CHZ 909952
CHASSIS NO : WAUZZZ8V1J1058418
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 21-Dec-21
PLACE OF ACCIDENT : 135 SUNSET WAY CAR PARK



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMA 3702 D

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION.	S/N \$ 280.00	\$ 280.00
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR LHS TAILLAMP PANEL AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 2,100.00	\$ 500.00
3	TO RESPRAY REAR BUMPER, LHS TAILLAMP PANEL AND REAR END PANELLING.	\$ 2,800.00	\$ 550.00
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	\$ 192.00
TOTAL LABOUR CHARGES		: \$ 5,372.00	\$ 1,522.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMA 3702 D

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 1,944.00	\$ 1,555.20
2	REAR BUMPER FIXING PARTS	1	\$ 193.00	
3	REAR BUMPER ADAPTER - LH	1	\$ 38.00	
4	REAR BUMPER GUIDE SECTION - LH / RH	1	\$ 32.00	
5	REAR BUMPER SPOILER	1	\$ 237.00	\$ 189.60
6	REAR LIGHT REFLECTOR - LH	1	\$ 41.00	
7	TAIL LIGHT - LH	1	\$ 877.00	\$ 701.60
8	TAIL LIGHT TRIM - LH	1	\$ 30.00	
9	REAR BUMPER SIDE REINFORCEMENT	1	\$ 603.00	
10	REAR BUMPER BRACKET - LH / RH	2	\$ 56.00	
11	REAR BUMPER GUIDE SECTION OUTER - LH	1	\$ 67.00	
12	REAR PARKING AID SENSOR	2	TBC	
13	REAR PARKING AID SENSOR SEAL RING	4	\$ 9.00	
14	REAR AIR VENT TRIM	1	\$ 68.00	
15	SUNDRIES		\$ 200.00	
TOTAL SPARE PARTS		:	\$ 4,395.00	\$ 2,446.40
TOTAL LABOUR CHARGES		:	\$ 5,372.00	\$ 1,522.00
GRAND TOTAL		:	\$ 9,767.00	\$ 3,968.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT