

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG21013269/ATCN2**Date:** 03/03/2022REFERENCE

Insured/Claimant: JOHN YEONG YING JUN (JOHN YANG YINGJUN) Policy No: 1800064094-03  
Date of Loss: 21/12/2021 Nature of Claim: OD Claim No: 5203872663SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA3702D**  
Make & Model: AUDI A3, 999cc SEDAN TFSI S TRONIC (LED) (A) Engine No: CHZ909952  
Reg. Date: 04/06/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V1J1058418  
Colour: Grey Odometer: 40562 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$87,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 205/55R16 Rear Tyre Size: 205/55R16  
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm  
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	4,395.00	2,446.40	1,948.60	44.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,372.00	1,522.00	3,850.00	71.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>9,767.00</b>	<b>3,968.40</b>	<b>5,798.60</b>	<b>59.37</b>
<b>- Excess (S\$)</b>	600.00	600.00	0.00	0.00
<b>(S\$)</b>	9,167.00	3,368.40	5,798.60	63.26
<b>+ GST 7.00/7.00% (S\$)</b>	641.69	235.79	405.90	63.25
<b>Nett Amount (S\$)</b>	<b>9,808.69</b>	<b>3,604.19</b>	<b>6,204.50</b>	<b>63.26</b>

INSPECTION

Date of Assignment: 29/12/2021  
Date Inspected: 28/12/2021 Inspected At: Premium Automobiles Pte Ltd (UBI)  
55 Ubi Road 1  
Singapore 408699  
Estimated Period of Repair: 3.0 days

**Adjuster:** ADRIAN LING**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,944.00 FS	*1,555.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	193.00 FS	*- FS
3	1		*REAR BUMPER ADAPTER-LH	Not Necessary	38.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION-LH/RH	Not Necessary	32.00 FS	*- FS
5	1		*REAR BUMPER SPOILER	Cut	237.00 FS	*189.60 FS
6	1		*REAR LIGHT REFLECTOR-LH	Not Necessary	41.00 FS	*- FS
7	1		*TAIL LIGHT-LH	Cracked	877.00 FS	*701.60 FS
8	1		*TAIL LIGHT TRIM-LH	Not Necessary	30.00 FS	*- FS
9	1		*REAR BUMPER SIDE REINFORCEMENT	Not Necessary	603.00 FS	*- FS
10	2		*REAR BUMPER BRACKET-LH/RH	Not Necessary	56.00 FS	*- FS
11	1		*REAR BUMPER GUIDE SECTION OUTER-LH	Not Necessary	67.00 FS	*- FS
12	2		*REAR PARKING AID SENSOR (Npa)	Not Necessary	0.00 FS	*- FS
13	4		*REAR PARKING AID SENSOR SEAL RING	Not Necessary	9.00 FS	*- FS
14	1		*REAR AIR VENT TRIM	Not Necessary	68.00 FS	*- FS
15	1		*SUNDRIES	Not Necessary	200.00 FS	*- FS

F=Franchise part. S=SpcNett.

**Total Parts (\$)**      **4,395.00**      **2,446.40**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE AND TRANSFER REAR PARKING AID.CHECK FUNCTION	New	280.00	280.00
2	TO DISMANTLE AND RENEW REAR BUMPER.TO REPAIR LHS TAILLAMP PANEL AND REAR END PANELLING.RE-ORGANIZE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	500.00
3	TO RESPRAY REAR BUMPER,LHS TAILLAMP PANEL AND REAR END PANELLING	New	2,800.00	550.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,522.00</b>
				<b>5,372.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >