

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/1051/2021/JT
DATE : 23-Dec-21
WIP : 59858

Veron.

\$3255.20.

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/12/21

AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
Attn: Motor Claims Dept
Tel: 6880 4602 - Fax: 6880 4838


OWNER'S NAME : MR TAN SENG SOON
ADDRESS : 9 VERDE CRESCENT
SINGAPORE 688364
TELEPHONE : HP +65 90844993
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 2070179457
VEHICLE NO : SMZ-1770Z SMX1770Z
MODEL CODE : AUDI A4 2.0 TFSI S TRONIC
MODEL YEAR : 29/12/2020
ENGINE NO : DEM 026664
CHASSIS NO : WAUZZZF40MA011296
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Dec-21
PLACE OF ACCIDENT : THE SLIP ROAD BETWEEN
PIE & THOMSON ROAD

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMX 1770 Z

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00	✓ ✓
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 350.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,050.00	500 ✓
4	TO RESPRAY FRONT BUMPER.	\$ 1,000.00	550 ✓
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓ ✓
TOTAL LABOUR CHARGES		: \$ 3,072.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2523 FAX: 6541 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 1770 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
1	FRONT BUMPER <i>Repair</i>	1	\$	2,233.00	X
2	FRONT BUMPER FIXING PARTS	1	\$	358.00	X
3	FRONT BUMPER SECURING STRIP	2	\$	71.00	+
4	FRONT BUMPER GRILLE - CENTER	1	\$	196.00	✓
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$	262.00	X
6	FRONT BUMPER AIR GUIDE - LH	1	\$	44.00	X
7	FRONT BUMPER CLOSING ELEMENT - UPPER CENTER	1	\$	262.00	+
8	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$	135.00	X
9	FRONT BUMPER TRIM - LH	1	\$	48.00	X
10	RADIATOR GRILLE	1	\$	1,580.00	✓ 1264
11	FRONT BUMPER FOAM FILLER PIECE	1	\$	189.00	✓ X
12	FRONT BUMPER REINFORCEMENT BEAM	1	\$	845.00	✓ X
13	FRONT BUMPER TOP COVER	1	\$	127.00	X
14	CAUTION STICKER	1	\$	14.00	✓
15	AIR COND STICKER	1	\$	8.00	✓
16	FRONT LOCK CARRIER BRACKET	1	\$	137.00	✓ X
17	FRONT BUMPER SUPPORT - LH / RH	2	\$	58.00	✓
18	POP RIVET	4	\$	4.00	+
19	FRONT PARKING AID SENSOR - INNER / OUTER	2	TBC		✓
20	FRONT PARKING AID SENSOR SEAL RING	4	\$	9.00	X
SUB TOTAL SPARE PARTS			:	\$ 6,580.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMX 1770 Z

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES		REMARKS
			S/NETT		
21	HEADLIGHT - LH {NE	1	\$	7,685.00	X
22	LIFT CYLINDER - LH }	1	\$	210.00	X
23	LIFT CYLINDER CORRUGATED PIPE xhe ~	1		TBC	X
24	FRONT NO PLATE Dented	S/N	\$	60.00	✓ 60
25	SUNDRIES Me Me		\$	250.00	? X
TOTAL SPARE PARTS			:	\$ 14,785.00	
TOTAL LABOUR CHARGES			:	\$ 3,072.00	
GRAND TOTAL			:	\$ 17,857.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6356 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME

: Adrian King

SURVEYED DATE

: 28/12/21

AUTHORISED DATE

:

EXCESS COST

:

LIABILITY

:

REMARKS

: Not Authorised, 03 Days
H.K.

PLEASE NOTE

: THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT