

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21013273/T1VF3N2**Date:** 06/01/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MR003734		
Claimant Vehicle No :	SH8579C	Insured Vehicle No :	GBG3248Y		
Date of Loss:	26/12/2021	Nature of Claim:	TP	Claim No:	M2106028

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8579C	Engine No:	D4FDEU419929
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU087121
Reg. Date:	14/04/2016 (Man. Year: 2015)	Odometer:	722825 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,246.42	695.70	550.72	44.18
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	800.00	560.00	240.00	30.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,057.42	1,266.70	790.72	38.43
Approved Total (Overridden) (S\$)		1,000.00		
(S\$)	2,057.42	1,000.00	1,057.42	51.40
+ GST 7.00/7.00% (S\$)	144.02	70.00	74.02	51.40
Nett Amount (S\$)	2,201.44	1,070.00	1,131.44	51.40

INSPECTION

Date of Assignment:	29/12/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	29/12/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Jan 2022)

Parts: 143 HYUNDAI I40 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SH8579C)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*REAR BUMPER	Deformed	553.00 FL	-	*553.00 FL
2	1		*REAR BUMPER UNDER COVER	Not Necessary	228.00 FL	-	*- FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	428.40 FL	-	*- FL
4	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	-	*22.00 FL
5	1		*REAR BUMPER REFLECTOR	Not Necessary	32.00 FL	-	*- FL
6	1		*REAR REVERSE SENSOR	Not Working	135.70 FS	-	*135.70 FS
7	1		*REAR BUMPER MAT	Necessary	50.00 FS	-	*50.00 FS
8	1		*REAR BUMPER ADVERTISEMENT	Necessary	50.00 FS	-	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,499.10	810.70
- List Item Discount on L Items 20.00/20.00% (\$\$)	252.68	115.00
Total Parts (\$\$)	1,246.42	695.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
Sub Total (\$\$)			11.00	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	280.00
2	SPRAY PAINTING	New	300.00	250.00
3	REMOVE/REFIX REVERSE SENSOR	New	60.00	30.00
4	TUFF COATING	New	40.00	0.00
Gross Labour Cost (\$\$)			800.00	560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >