ASS. REC. BY: Tayph REF: CS [TM] Z	1013273/Tivfs
ASSI	IGNMENT (
From: Date:	Veh No: \$48579C Yr Regn: 2961 April
From: Date:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD (TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Hynder 140 c.c 1685
	Colour A/C: Insured / Std / NI / NA
at Workshop m/s of	Sp.Reading 72287 T/Radio; Insured / Std / NI / NA
Insured: GBG 3248Y	Eng/No:
Policy No. MR003734	C/No: KMULB4/44994087/21
Claims No. M2106028	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: (Nil / S/Rim / STD A/Rim or
	Tyre Size: F: 205/60R16
(Policy Condition)	R: 1
Remark: The veh had commenced its N/S O/S	
repair at the time of inspection.	TOYO I YOKO or we Mehr
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. mm R/Bal.
GIA / PR Seen:Consistent? : Yes or No	L/Bal. L/Bal. 6 mm
Est. Repairs:days Res.: Yes or No	D.O.A. 15/12/21 D.O.I. 29/12/2)
Lum Sum: % 3 Val.: Yes or No	Survey held at Carfut Course
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/O	The U/C / Chassis frame / Body Structure affected due to collision.
Date: Person Contacted: Contacted: Date / Time Action / Instruction	
Date / Time Action / modassey	·
5/1/22 LS \$1000 confirmed by email (Red 10	057.42,51%)
1	
Dut Tim Tile Density	Days Of Repair: 2
Date/Time, File Pass to? : Preli. Report	Resurvey No. of Trip: 1 Survey Fee:
1) : Final Report Date/Time, File Return to?	Transportation:
	Fee: : Site Insp (\$)_s+RSSI
2) 0/ 1/22-19 1/31	: Interview (\$) Photos
Rep Format: Merimen	: Tech. Invs (\$) Others
Lump Sum / I.B.A: (F \$1000)	: Weel:end (%
	TOTAL
the state of the s	

Repairer Estimates

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive Singapore 508969 Tel: 6214 8300

TP INSURER:

Tokio Marine Insurance Singapore Ltd (HQ)

CTPL

Singapore

PARTICULARS OF CL	AIM				
Claim Type:	THIRD PARTY	Ref. No:			
Policy No: Date of Loss:			26/12/2021		
Vehicle Reg. No.:	SH8579C	Driveable?	YES		
Party At Fault:	UNKNOWN				
Make/Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Vehicle Reg. Date:	14/04/2016		
Vehicle Colour:	BLUE	Gen Condition:	GOOD		
Engine No:	D4FDEU419929	Chassis No:	KMHLB41UMGU087121		
Odometer:	722546 KM				
Paint Type:					
List Item Discount:	20.00 %				
Total Loss?	NO				
Est. Duration of Repair	2				
(day)	2				
Present Location:	COMFORTDELGRO ENGINEERING	G PTE LTD (LOYANG)			
COST OF CLAIMS			Amount		
Parts			1,246.42		
Miscellaneous Items			11.00		
Labour			800.00		
Paintwork Labour			0.00		
Towing			0.00		

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Gross Total (S\$)

+ GST 7.00% (S\$) Nett Amount (S\$) 2,057.42 144.02

2,201.44

REPAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 29 Dec 2021)

Parts: Labour: 143

HYUNDAI 140 1.7 D CRDI F/L ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)

Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH8579C/29/12/2021 09:32

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

	Qty Part No.	Particulars	%Disc	%Depr	Amount
1	1	*REAR BUMPER	20.00	0.00	de /*553.00 FL
2	1	*REAR BUMPER UNDER COVER	20.00	0.00	★ *228.00 FL
3	1	*REAR BUMPER REINFORCEMENT	20.00	0.00	7 *428.40 FL
4	10	*REAR BUMPER CLIPS	20.00	0.00 4	22.00 FL
5	1	*REAR BUMPER REFLECTOR	20.00	0.00	X *32.00 FL
6	1	*REAR REVERSE SENSOR	0	0.00	nu *135.70 FS
7	1	*REAR BUMPER MAT	0	0.00	*50.00 FS
8	1	*REAR BUMPER ADVERTISEMENT	0	0.00	14 *50.00 FS
F=Fra	anchise part. S=SpcNett	L=ListItemDisc.			
			\$ub Total (S\$)		1,499.10
		- List Item Disc	count on L Items (S\$)		252.68
			Total Parts (S\$)		1,246.42

ComfortDelGro Engineering Pte Ltd/SH8579C/29/12/2021 09:32. Not valid without Reference section. Generated using Merimen e-Claim's IEAS

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tanphin 17/15749

ap' 21/2/21 C415pm

2 deys
4/5 Resury after report

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting
To display damaged part(s) during resurvey

Parts prices are subject to confirmation
Third party survey is or, a "Without Prejudice" basis
No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signatur

Date:



ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701 Maintine + 65 6383 6280 Facsimile + 65 6280 9750

REGN NO.: 8579C

HYUNDAI

Page

Team:

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4157163

Date/Time: 29.12.2021 09:08

JC NO305499561

MILEAGE

FUEL

E.....

CUSTOMER COMFORT TRANSPORTATION PTE LTD MR/MS 7010045 CUSTOMER NO. 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755 TEL. (R) (O) (P)

YR OF MANU. 14.04.2016 CHASSIS CODE KMHLB41UMGU087121 TARGET DATE

COMPLETION DATE/TIME

DISCOUNT CARD NO.

Accident Date: 26.12.2021


NATURE: 3P 26.12.2021

S/NO

LABOR CODE

DESCRIPTION

JOB DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

cknowledgement Slip

ame:

C No.: shicle No.:

SH 8579C

CHIANG

Vehicle No.:

Exit Pass

SH 8579C

ame of Service Advisor

Signature/Date

Name of Service Advisor

Date

) be returned to Service Reception upon collection

To be kept by Security Guard