



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
ECICS LTD 10 EUNOS ROAD 8 SINGAPORE POST CENTRE #09-04A SINGAPORE 408600		Ref: CS/ICS21013274/R1tf3 Date: 29/12/2021	Code: ICS
<b>1. Policy Particulars :- OWN DAMAGE</b>			
<b>Insured Veh.</b>	<b>Veh. Inspected</b>	SLR 3584A	
<b>Policy No.</b>	<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b> MPC21P00150000	<b>Excess (\$)</b>	0.00	
<b>Assign From</b> MERIMEN (LIU CHUN CHEONG)	<b>Assign Date</b>	29/12/2021	
<b>2. Vehicle Particulars &amp; Condition</b>			
<b>Make &amp; Model</b>	<b>c.c</b>	0	
<b>Engine No.</b> HIDDEN	<b>Year of Reg.</b>		
<b>Chassis No.</b>	<b>Colour</b>		
<b>Odometer</b> -	<b>Steering</b>		
<b>Brakes</b>	<b>Modification</b>		
<b>General</b>			
<b>3. Conditions of Tyres</b>			
	<b>Size</b>	<b>Make</b>	<b>Balance</b>
<b>R/H Front Tyre</b>			mm
<b>L/H Front Tyre</b>			mm
<b>R/H Rear Tyre</b>			mm
<b>L/H Rear Tyre</b>			mm
<b>4. Description of Damages</b>			
<b>5. General Information</b>			
<b>Accident Date</b> 24/12/2021	<b>Inspection Date</b>	30/12/2021	
<b>Survey held at</b>	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		
<b>5a. Remarks</b>			
A) THE MARKET VALUE IS S\$----- (EST. AVERAGE) B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			