

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Nor Azian Binte Noordin

Date: 11 Jan 2022

Preliminary Advice

Insured Vehicle No	: SMY7591D	Accident Date	: 27/12/2021
TP Vehicle No	: SMG2822R	Assignment Date	: 29/12/2021
Make	: PEUGEOT 308	Est. Duration of Repair	: 3
Date of Inspection	: 29/12/2021		
Inspection At	: ZOOM AUTOWERKS PTE LTD (HQ) 15 KAKI BUKIT ROAD 4, #01-53 SINGAPORE 417808		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,477.60
Revised Amount	:S\$	2,634.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	2,634.50
Lump Sum Repair	:S\$	2,100.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	71,000.00
COE / PARF Rebate	:S\$	33,726.00
Salvage Value	:S\$	
Margin for Repair	:S\$	37,274.00

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- (X) Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.