

SR AUTOWORKS PTE LTD.

Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875

Email: srautoworks.claims@gmail.com

Tel: 6286 6060 Fax : 6286 7060

Office Use Only

Parts -10%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	33K

TO: AIG

Vehicle No : GBH 4914 X

Make & Model : NISSAN NV200

DATE: 23/12/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAILGATE LH	1	\$ 1,684.00	\$ 1,684.00
2	TAILGATE LOGO	1	\$ 89.00	\$ 89.00
3	TAILGATE STICKER (NV200)	1	\$ 97.80	\$ 97.80
4	TAILGATE HINGE LH	2	\$ 120.00	\$ 240.00
5	TAILGATE CHECKER LH	1	\$ 135.40	\$ 135.40
6	TAILGATE OUTER GARNISH LH	1	\$ 345.00	\$ 345.00
7	TAILGATE NUMBER PLATE LAMP	2	\$ 90.00	\$ 180.00
8	TAILGATE OPENER HANDLE LH	1	\$ 124.90	\$ 124.90
9	TAILGATE LOWER LOCK LH	1	\$ 415.40	\$ 415.40
10	TAILGATE LOWER LOCK CATCH LH	1	\$ 89.00	\$ 89.00
11	TAILGATE LOCK MECHANISIM LH	1	\$ 357.10	\$ 357.10
12	TAILGATE INNER BOARD LH	1	\$ 445.90	\$ 445.90
13	TAILGATE GLASS INNER SEAL LH	1	\$ 50.00	\$ 50.00
14	TAILGATE FRAIM WEATHERSTRIP	1	\$ 255.60	\$ 255.60
15	REVERSE CAMERA	1	\$ 1,458.00	\$ 1,458.00
16	TAILGATE RH	1	\$ 1,093.00	\$ 1,093.00
17	TAILGATE HINGE RH	2	\$ 120.00	\$ 240.00
18	TAILGATE SIDE OPENER HANDLE RH	1	\$ 109.80	\$ 109.80
19	TAILGATE LOWER LOCK RH	1	\$ 415.40	\$ 415.40
20	TAILGATE LOWER LOCK CATCH RH	1	\$ 89.00	\$ 89.00
21	TAILGATE INNER BOARD RH	1	\$ 299.00	\$ 299.00
22	TAILGATE WEATHERSTRIP RH	1	\$ 245.70	\$ 245.70
23	TAILGATE SIDE RUBBER	1	\$ 127.30	\$ 127.30
24	TAILGATE GLASS INNER SEAL RH	1	\$ 50.00	\$ 50.00
25	TAIL LAMP	2	\$ 289.00	\$ 578.00
26	REAR BUMPER	1	\$ 489.00	\$ 489.00
27	REAR BUMPER SPONGE	1	\$ 135.00	\$ 135.00
28	REAR BUMPER SIDE RETAINER	1	\$ 88.90	\$ 88.90
29	REAR BUMPER REFLELCTOR	2	\$ 127.00	\$ 254.00
30	REAR BUMPER BOTTOM BRACKET	4	\$ 56.00	\$ 224.00

RMX

[illegible]

LABOUR		PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS		\$ 1,800.00
TO SPRAY PAINT AFFECTED AREA		\$ 1,600.00
WIRING, BULB CHECKING		\$ 50.00
REMOVE AND REFIX BOTH TAILGATE WINDSCREEN		\$ 300.00
TRANSFER BOTH TAILGATE MECHAISM		\$ 300.00
CONDUCT WATER LEAKAGE TEST		\$ 100.00
REMOVE AND REFIT REAR RACK TO FACILIATE REPAIR		\$ 300.00
REAR CHASSIS ALIGHMENT		\$ 300.00
REMOVE AND REFIX REAR REVERSE SENSOR		\$ 150.00
REMOVE AND REFIX REAR REVERSE CAMERA		\$ 180.00
REMOVE AND INSTALL CARPET ,TRIM AND INTERIOR		\$ 400.00
	LABOUR TOTAL	\$ 5,480.00
	Total Parts Cost	\$ 17,523.28
	Total Labour Cost	\$ 5,480.00
	Total Repair Cost	\$ 23,003.28

APPROVED DETAILS

Tamplin 9749549
'wp' 29/12/71 C 12 pm
L/S Reentry after repair
tamplin elephantown
7 days

LKK Auto Consultants hence notify
the Repairer of the following: