

SR AUTOWORKS PTE LTD.

Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875

Email: srautoworks.claims@gmail.com

Tel: 6286 6060 Fax : 6286 7060

Office Use Only

Parts -10%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	33K

TO: AIG

Vehicle No : GBH 4914 X

Make & Model : NISSAN NV200

DATE: 23/12/2021

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE
1	TAILGATE LH 1469.60	1	\$ 1,684.00	\$ 1,684.00
2	TAILGATE LOGO	1	\$ 89.00	\$ 89.00
3	TAILGATE STICKER (NV200)	1	\$ 97.80	\$ 97.80
4	TAILGATE HINGE LH	2	\$ 120.00	\$ 240.00
5	TAILGATE CHECKER LH	1	\$ 135.40	\$ 135.40
6	TAILGATE OUTER GARNISH LH	1	\$ 345.00	\$ 345.00
7	TAILGATE NUMBER PLATE LAMP	2	\$ 90.00	\$ 180.00
8	TAILGATE OPENER HANDLE LH	1	\$ 124.90	\$ 124.90
9	TAILGATE LOWER LOCK LH	1	\$ 415.40	\$ 415.40
10	TAILGATE LOWER LOCK CATCH LH	1	\$ 89.00	\$ 89.00
11	TAILGATE LOCK MECHANISIM LH	1	\$ 357.10	\$ 357.10
12	TAILGATE INNER BOARD LH	1	\$ 445.90	\$ 445.90
13	TAILGATE GLASS INNER SEAL LH	1	\$ 50.00	\$ 50.00
14	TAILGATE FRAIM WEATHERSTRIP 215	1	\$ 255.60	\$ 255.60
15	REVERSE CAMERA	1	\$ 1,458.00	\$ 1,458.00
16	TAILGATE RH	1	\$ 1,093.00	\$ 1,093.00
17	TAILGATE HINGE RH	2	\$ 120.00	\$ 240.00
18	TAILGATE SIDE OPENER HANDLE RH	1	\$ 109.80	\$ 109.80
19	TAILGATE LOWER LOCK RH	1	\$ 415.40	\$ 415.40
20	TAILGATE LOWER LOCK CATCH RH	1	\$ 89.00	\$ 89.00
21	TAILGATE INNER BOARD RH	1	\$ 299.00	\$ 299.00
22	TAILGATE WEATHERSTRIP RH	1	\$ 245.70	\$ 245.70
23	TAILGATE SIDE RUBBER	1	\$ 127.30	\$ 127.30
24	TAILGATE GLASS INNER SEAL RH	1	\$ 50.00	\$ 50.00
25	TAIL LAMP RMX	2	\$ 289.00	\$ 578.00
26	REAR BUMPER	1	\$ 489.00	\$ 489.00
27	REAR BUMPER SPONGE	1	\$ 135.00	\$ 135.00
28	REAR BUMPER SIDE RETAINER	1	\$ 88.90	\$ 88.90
29	REAR BUMPER REFLELCTOR	2	\$ 127.00	\$ 254.00
30	REAR BUMPER BOTTOM BRACKET	4	\$ 56.00	\$ 224.00

32	REAR BUMPER TOW COVER	1	\$	45.00	\$	45.00	nn
33	REAR END PANEL (INNER)	1	\$	879.00	\$	879.00	nn
34	REAR END PANEL (OUTER)	1	\$	258.00	\$	258.00	nn
35	REAR END PANEL TOP GARNISH	1	\$	125.00	\$	125.00	nn
36	REAR FLOOR PANEL	1	\$	1,564.00	\$	1,564.00	nn
37	REAR SPARE TYRE HOLDER BRACKET	1	\$	548.00	\$	548.00	nn
38	REAR SPARE TYRE HOLDER BOLT	1	\$	60.00	\$	60.00	nn
39	REAR EXHAUST PIPE	1	\$	689.00	\$	689.00	nn
40	REAR EXHAUST MOUNTING	1	\$	65.00	\$	65.00	nn
41	REAR EXHAUST BRACKET	1	\$	121.00	\$	121.00	nn

				3688.40	Subtotal :	\$	14,759.20
				3319.56	Less 10%	\$	1,475.92
					Parts Total :	\$	13,283.28

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	REAR NUMBER PLATE	1	\$	50.00	\$ 50.00
2	REAR BUMPER CLIP	1	\$	60.00	\$ 30 60.00
3	TAILGATE SEALANT	1	\$	80.00	\$ 80.00
4	TAILGATE COMPANY STICKER	1	\$	500.00	\$ 100 500.00
5	TAILGATE STICKER(70KM/H)	1	\$	50.00	\$ 30 50.00
6	TAILGATE STICKER(5 PAX)	1	\$	50.00	\$ 10 50.00
7	TAILGATE OUTER GARNISH CLIP	1	\$	50.00	\$ 50.00
8	TAILGATE INNER BOARD CLIP LH	1	\$	40.00	\$ 40.00
9	TAILGATE WINDSCREEN SEALANT	2	\$	80.00	\$ 160.00
10	TAILGATE WINDSCREEN INNER SEAL	2	\$	80.00	\$ 160.00
11	TAIL LAMP CLIP	1	\$	30.00	\$ 30.00
12	REAR FLOOR PANEL MAT	1	\$	800.00	\$ nn 800.00
13	REAR FLOOR PANEL TOP BOARD	1	\$	800.00	\$ 200 800.00
14	REAR END PANEL (INNER) SEALANT	1	\$	150.00	\$ 150.00
15	REAR END PANEL (OUTER) SEALANT	1	\$	150.00	\$ 150.00
16	REVERSE SENSOR	1	\$	380.00	\$ 380.00
17	REVERSE CAMERA	1	\$	650.00	\$ 650.00
18	REAR FLOOR PANEL SEALANT	1	\$	80.00	\$ 80.00
					\$ 470 470
					\$ 4,240.00

LABOUR	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00 500
TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00 1500
WIRING, BULB CHECKING	\$ 50.00 2000
REMOVE AND REFIX BOTH TAILGATE WINDSCREEN	\$ 300.00 120
TRANSFER BOTH TAILGATE MECHAISM	\$ 300.00 100
CONDUCT WATER LEAKAGE TEST	\$ 100.00 30
REMOVE AND REFIT REAR RACK TO FACILIATE REPAIR	\$ 300.00 400
REAR CHASSIS ALIGHMENT	\$ 300.00 400
REMOVE AND REFIX REAR REVERSE SENSOR	\$ 150.00 30
REMOVE AND REFIX REAR REVERSE CAMERA	\$ 180.00 200
REMOVE AND INSTALL CARPET ,TRIM AND INTERIOR	\$ 400.00 3000
	1280
LABOUR TOTAL	\$ 5,480.00

	Total Parts Cost	\$ 17,523.28
	Total Labour Cost	\$ 5,480.00
	Total Repair Cost	\$ 23,003.28

APPROVED DETAILS
NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphu 9749549
 'wp' 29/12/11 12pm
 L/S Repair after repair
 Tanphu @ 11/12/11
 17 days
 5 days
 3319.56
 470
 1280
 5069.56
 4544000
 5 days
 us\$ 4000, 5 days