Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD482B

AAD2112-

Not Asthorital USmy & 950/

	Vehicle No.:		SHD4821	В	
	Chassis No.:		VF1ABL1	5AUC283292	
	Vehicle Make: A la Margara para Margara	27 DEC 2021	RENAULT	F 40 6 6	
	venicle Model:		LATITUDE	E	
	Date of Accident : 100 100 100 100 100 100 100 100 100 1	detta in d	24/12/20	21	
	Third Party Insurer:		AIC.		
	Date of Registration:		07/08/20		
	in their and records that exhaust pay		11	1740	
	PART BUMPER COVER EDT			LIST	
1	- OWN THE COATH LKI		\$	7 747.20	
1	SOME EN NETATIVER PRI LH		\$	101.4	
1			\$	743.60	
1	THE POST OF THE PARTY OF THE PA	erracing of expo	\$	128.30) X
1	. THE ENTINIALL INTELL		\$	437.10	
1	The state of the s		\$	Per 191.40	
1	THE CELL HALIN EOANEN	and contract	\$	ر الم	- V
1	A LIK CLEANINE TO TO THE		\$	رم 175.8!	
1	AIR CLEANER BOX		\$	1ec 464.20	
		and the second	\$	3,260.31	
	To creed recomp geometry and mag	10%	\$	326.03	<u></u>
			\$	2,934.28	<u> </u>
	Specical Nett				
1SET	BUMPER BRACKET SIDE CLIP LH RR		\$	na 10.00	X
1SET	BUMPER RETAINER CLIP LH RR		\$	na 20.00	130
1	BUMPER CLIP FRT		\$	ル _{~ 85.00}	
1	FENDER LINER CLIP		\$	an 65.00	,
		TOTAL	\$	180.00	
		TOTAL PARTS	\$	3,114.28	_
	A service and the service and the	direct com		N .	
	LABOUR	Review Days		Tare 1	
Putty And Spray Painting Of The Affected Portion.				3,000.00	3001
	Panel Beating, Knocking And Straighter	ning The			
Necessary Portion, Remove And Renewal Of Parts,				3,000.00	4401
1	Adjust And Realign The Same				

Trans-cab Auto Services Pte Ltd

AAD2112-

No. 2 Ang Mo Kio Street 63 Singapore 569111 Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHD482B

	A H . P . Water Land Co.		
To Rust-Proofing Of Th	e Affected Areas.	\$	170.00 30
To reinstall rear bumpe	r parking sensor.		Na 170.00 X
To transfer of bootlid fit perform water seepage		.	ح 170.00 م
To repair and realign rea	ar exhaust pipe.	\$	ر 170.00 X
To drop rear exhaust bo	ox, renew the same, to r ust pipe.	epair \$	5 170.00 X
To transfer of rear end perform water seepage	panel fittings, attachme test.	nt and \$	4 170.00 X
To transfer of rear winds water seepage test.	Yes	luct \$	5 170.00 X
To check steering geome alignment	etry and computer whe	el \$	℃ 220.00 ⊀
	Administra Landaria		
To Check Electrical Light	ting Concerned.	\$	170.00 /5/
ries, and the collection of the part of sufficient prints for the prints of the collection of the coll		TOTAL \$	7,580.00
	Over A	II Total \$	13,628.56
LKK Auto Consultants the Repairer of the followater of the followa	owing: ray painting during resurvey confirmation Without Prejudice" basis allowed by the resurveyed and	P SUM) air Days	POTAYS Zday,
Acknowledged by Repairer Signature: Date:	A HARANE LIPE		