

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

GBC9119T
TP/AIG

M/S: AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000
ATTN: Motor Claim Department

FAX: 64153727

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 28/12/2021
TP Veh Reg No: GZ5550B

Estimate No: ES2191277/YISHUN
Date: 29 Dec 2021
Policy No: DMCVSNW00005552101
Veh Reg No: GBC9119T
Make/Model: TOYOTA TOYOTA
DYNA 150 5MT
Chassis No: JTFAT35Y20K213751
Engine No: 1KD2860557
Reg. Date: 26/07/2019

Estimate Repair Cost to Vehicle No :GBC9119T

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 FRONT BUMPER	718.90	1 PC	718.90	✓
2 FRONT BUMPER BRACKETS	299.50	2 PCS	599.00	✓
3 FRONT GRILLE	577.50	1 PC	577.50	✓
4 FRONT GRILLE LOGO	71.00	1 PC	71.00	✓
5 FRONT GRILLE CLIPS	3.50	6 PCS	21.00	✓
6 RH HEADLAMP	1,078.70	1 PC	1,078.70	✓
7 FRONT PANEL	1,094.30	1 PC	1,094.30	✓
8 FRONT PANEL EMBLEM (DYNA)	67.00	1 PC	67.00	✓
9 FRONT WIPER PANEL	311.80	1 PC	311.80	✓
10 FRONT WIPER LINKAGE	318.90	1 PC	318.90	✓
11 FRONT RH DOOR REAR PILLAR EMBLEM (D4D)	49.60	1 PC	49.60	✓
12 AIRCON EVAPORATOR	2,674.00	1 PC	2,674.00	✓
13 RH TAILLAMP	222.10	1 PC	222.10	✓
14 TAILLAMP PANELS	66.20	2 PCS	132.40	✓
15 REAR NUMBER PLATE GARNISH	172.20	1 PC	172.20	✓
			8,108.40	
		Less 25%	2,027.10	6,081.30
Special Net				
16 REAR NUMBER PLATE	20.00	1 PC	20.00	✓
17 REVERSE SENSOR	200.00	1 SET	200.00	✓
18 FRONT NUMBER PLATE	20.00	1 PC	20.00	✓
19 RH TAILGATE WITH INNER STAINLESS STEEL PROTECTOR	1,450.00	1 PC	1,450.00	✓
20 RH TAILGATE BOTTOM HINGE	180.00	1 PC	180.00	✓
21 RH TAILGATE TOP HINGE	180.00	1 PC	180.00	✓
22 RH TAILGATE OPENNER	390.00	1 PC	390.00	✓
23 LH TAILGATE WITH INNER STAINLESS STEEL PROTECTOR	1,450.00	1 PC	1,450.00	✓
24 STICKER - 70KM/H	10.00	1 PC	10.00	✓
			3,900.00	3,900.00
Labour				
25 REMOVE AND REFIX FRONT WINDSCREEN GLASS	60.00	1 LA	60.00	✓
26 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
27 REMOVE & REFIX DASHBOARD,METER ASSY AND CHECK WIRING	280.00	1 LA	280.00	25d

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000
ATTN: Motor Claim Department

FAX: 64153727

WS Ref: TP/AIG
Claim Type: Third Party
Accident Date: 28/12/2021
TP Veh Reg No: GZ5550B

Estimate No: ES2191277/YISHUN
Date: 29 Dec 2021
Policy No: DMCVSNW00005552101
Veh Reg No: GBC9119T
Make/Model: TOYOTA TOYOTA
DYNA 150 5MT
Chassis No: JTFAT35Y20K213751
Engine No: 1KD2860557
Reg. Date: 26/07/2019

Estimate Repair Cost to Vehicle No :GBC9119T

Description	U/Price	Quantity	List Price	Amount
28 REMOVE & REFIX FRT BUMPER ASSY,HEADLAMPS,GRILLE,FRT WIPER PANEL & WIPER ASSY,CUT,WELD & RENEW FRT PANEL,STRAIGHTEN,KNOCK & REPAIR FRT RH W/SCREEN PILLAR,CABIN REAR RH PILLAR,REPAIR,REALIGN CABIN FRT CROSS BAR & REALIGN CABIN POSITION	1,000.00	1 LA	1,000.00	800
29 REMOVE & REFIX NUMBER PLATE BRACKET,TAILLAMP & BRACKETS,STRAIGHTEN,KNOCK & REPAIR REAR TRUCK END MEMBER,FLOOR BOARD AND REALIGN THE SAME	800.00	1 LA	800.00	700
30 PUTTY & RESPRAY ON FRT PANEL,WIPER PANEL,FRT GRILLE,FRT BUMPER,FRT RH DOOR REAR PILLAR AND FRT AFFECTED AREAS	800.00	1 LA	800.00	720
31 PUTTY & RESPRAY REAR TRUCK END CROSS MEMBER AND FLOOR BOARD	500.00	1 LA	500.00	?
32 REMOVE & REFIX TAILGATES,REPLACE TAILGATE INNER STAINLESS STEEL,REMOVE & REFIX REAR DAMAGE STAINLESS STEEL DECKING AND CANOPY & CHECK LEAKING	2,000.00	1 LA	2,000.00	1500
33 TO REWRITE ADVERTISEMENT	1,000.00	1 LA (B.11)	1,000.00	?
			6,540.00	6,540.00
			Total	S\$ 16,521.30
			Add GST @ 7%	1,156.49
			Total Amount Payable	S\$ 17,677.79

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE