

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013285/GQY3E2**Date:** 17/01/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00014802100

**Claimant Vehicle
No :** SMN9256S**Insured Vehicle
No :** SJR154B

Date of Loss: 21/12/2021

Nature of Claim: TP

Claim
No: SNM21D207548/C02/TANKLDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SMN9256S**

Make & Model: TOYOTA PRIUS, 1.8 PLUS (A)

Engine No: 2ZR0E45184

Reg. Date: 30/08/2019 (Man. Year: 2019)

Chassis No: JTDZS3EU40J046536

Colour: Grey

Odometer: 194970 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size: 205/60 R16

Front Left Side: Firenza 6 mm

Rear Left Side: Firenza 6 mm

Front Right Side: Firenza 6 mm

Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,589.50	1,765.25	4,824.25	73.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,490.00	1,510.00	980.00	39.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,079.50	3,275.25	5,804.25	63.93
Approved Total (Overridden) (S\$)		2,600.00		
(S\$)	9,079.50	2,600.00	6,479.50	71.36
+ GST 7.00/7.00% (S\$)	635.57	182.00	453.57	71.36
Nett Amount (S\$)	9,715.07	2,782.00	6,933.07	71.36

INSPECTION

Date of Assignment: 28/12/2021

Date Inspected: 27/12/2021 Inspected At:

My Car Consultant Pte Ltd (Jalan Lam Huat) (HQ)
60 Jalan Lam Huat, Carros Centre #05-21
Singapore 737869

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Jan 2023)
Parts:	144	TOYOTA PRIUS 1.8 PLUS (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMN9256S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Repair	798.00 FL	*- FL
2	1		*FRONT FENDER LH	Not Necessary	698.00 FL	*- FL
3	1		*FRONT FENDER COWLING	Torn	159.00 FL	*159.00 FL
4	1		*FRONT FENDER EMBLEM HYBRID	Necessary	68.00 FL	*68.00 FL
5	1		*FRT LOWER ARM LH	Not Necessary	581.00 FL	*- FL
6	1		*FRT KNUCKLE ARM LH	Not Necessary	587.00 FL	*- FL
7	1		*FRT WHEEL BEARING LH	Not Necessary	198.00 FL	*- FL
8	1		*FRT WHEEL SHOCK ABSORBER LH	Not Necessary	468.00 FL	*- FL
9	1		*FRONT DOOR LH	Buckled	1,258.00 FL	*1,258.00 FL
10	2		*FRONT DOOR HINGES LH	Not Necessary	136.00 FL	*- FL
11	1		*FRONT DOOR WEATHERSTRIP LH	Not Necessary	212.00 FL	*- FL
12	1		*FRONT DOOR INNER LOCK LH	Not Necessary	298.00 FL	*- FL
13	1		*FRONT DOOR REGULATOR LH	Not Necessary	698.00 FL	*- FL
14	1		*FRONT DOOR INNER TRIM BOARD LH	Not Necessary	598.00 FL	*- FL
15	1		*REAR FENDER LH	Repair	651.00 FL	*- FL
16	1		*SIDE SKIRTING LH	Cut	898.00 FL	*722.00 FL
17	1		*SET FRT BUMPER CLIP	Not Necessary	50.00 FS	*- FS
18	1		*FRONT SPORTS RIM LH (LOCAL REPAIR)	Damaged	80.00 FS	*80.00 FS
19	1		*FRONT TYRE LH	Not Necessary	180.00 FS	*- FS
20	1		*SET FRT FENDER INNERSHIELD CLIP LH	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,666.00	2,317.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	2,076.50	551.75
Total Parts (\$\$)	6,589.50	1,765.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	100.00	50.00
2	R+R FRT FENDER QUARTER GLASS RH	New	120.00	0.00
3	CONDUCT WHEEL ALIGNMENT	New	150.00	60.00
4	REMOVE AND REFIT UNDERCARRIAGE	New	400.00	0.00
5	REALIGN HEADLAMP	New	120.00	0.00
6	KNOCK	New	600.00	400.00
7	SPRAY	New	1,000.00	1,000.00
Gross Labour Cost (\$\$)			2,490.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >