

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Cecilia Lee

Date: 30 Dec 2021

Preliminary Advice

Vehicle No	: SMJ2407R	Accident Date	: 26/12/2021
Make	: BMW 520I	Policy No.	: DMPCSNW00029022102
Assignment Date	: 29/12/2021	Excess	: S\$1,250.00
Date of Inspection	: 30/12/2021	Est. Duration of Repair	: 10
Inspection At	: DING AUTO PTE LTD (HQ) 176 SIN MING DRIVE #04-06, SIN MING AUTOCARE SINGAPORE 575721		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 27,500.47
Revised Amount	:S\$ 20,033.82
Check Items (Estimated)	:S\$ 2,866.65
Total	:S\$ 22,900.47

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 44,000.00
COE / PARF Rebate	:S\$ 31,168.00

Salvage Value	:S\$
Margin for Repair	:S\$ 12,832.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : PENDING REPAIR COST FROM REPAIRER.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.