

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI21013287/T1VF3N2**Date:** 21/01/2022REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MQ004743
Claimant Vehicle No :	SHB4811U	Insured Vehicle No :	EB2288D
Date of Loss:	28/12/2021	Nature of Claim:	TP
		Claim No:	M2106029

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB4811U		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Engine No:	2ZRS061460
Reg. Date:	13/09/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FUX03563330
Colour:	Yellow	Odometer:	529629 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,221.26	2,312.17	2,909.09	55.72
Miscellaneous Items	11.00	11.00	0.00	0.00
Labour	1,595.00	1,115.00	480.00	30.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,827.26	3,438.17	3,389.09	49.64
Approved Total (Overridden) (S\$)		2,750.00		
(S\$)	6,827.26	2,750.00	4,077.26	59.72
+ GST 7.00/7.00% (S\$)	477.91	192.50	285.41	59.72
Nett Amount (S\$)	7,305.17	2,942.50	4,362.67	59.72

INSPECTION

Date of Assignment:	29/12/2021	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	29/12/2021	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	3.0 days		

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jan 2022)

Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHB4811U)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Reference	Amount
1	1		*FRONT BUMPER	Torn	499.90 FL	-	*499.90 FL
2	1		*FRONT BUMPER BRACKET LH/RH	Not Necessary	82.30 FL	-	*- FL
3	1		*FRONT FENDER RH	Bent	945.30 FL	-	*945.30 FL
4	1		*FRONT FENDER SHIELD RH	Torn	198.50 FL	-	*198.50 FL
5	1		*FRONT FENDER EMBLEM RH	Necessary	86.50 FL	-	*86.50 FL
6	1		*FRONT BUMPER RETAINER RH	Missing	86.30 FL	-	*86.30 FL
7	1		*FRONT HEAD LAMP RH	Not Necessary	2,735.28 FL	-	*- FL
8	1		*FRONT DAY LIGHT RH	Cut	920.00 FL	-	*920.00 FL
9	1		*FRONT WHEEL COVER RH	Cut	346.40 FL	-	*346.40 FL
10	1		*FRONT HEAD LAMP PANEL RH	Not Necessary	240.10 FL	-	*- FL
11	1		*FRONT HEAD LAMP MOUNTING RH	Not Necessary	25.50 FL	-	*- FL
12	1		*FRONT SUPPORT RADIATOR RH	Not Necessary	83.50 FL	-	*- FL
13	1		*FRONT SUPPORT RADIATOR LOWER	Not Necessary	225.40 FL	-	*- FL
14	1		*FRONT WIPER SPARE TANK ASSY	Not Necessary	486.70 FL	-	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	6,961.68	3,082.90
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,740.42	770.73
Total Parts (\$\$)	5,221.26	2,312.17

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	OD/TP Case (Insurer)	11.00	11.00
			Sub Total (\$\$)	11.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	875.00	525.00
2	SPRAY PAINTING	New	600.00	500.00
3	CHECK WIRING	New	60.00	30.00
4	RESET WHEEL ALIGNMENT	New	60.00	60.00
			Gross Labour Cost (\$\$)	1,595.00
				1,115.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >