

ASS. REC. BY: Taufikh REF: CS/7M/21013287/T16f3

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: EB 2288D
 Policy No. MQ004743
 Claims No. M2106029
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: S4B4811U Yr Regn: 2017, Sep
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: toyota prius c.c. 1798
 Colour: yellow A/C: Insured / Std / NI / NA
 Sp. Reading: 529629 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: J TDKB3 FU X03563330
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Modi: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: 21

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

| | |
|-----|-----|
| N/S | O/S |
| | |

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Westlake
 Front R/Bal. 6 mm Rear R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 28/12/21 D.O.I. 29/12/21
 Survey held at Comfort Logon
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Frt of S
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: Amoy Vehicle: IN / OUT

| Date / Time | Action / Instruction |
|-------------|---|
| 19/1/22 | Taufikh informed LS \$2750 (Red 4077.26, 59%) |
| | |
| | |
| | |
| | |

Date/Time, File Pass to? : Preli. Report : Final Report
 1) _____
 Date/Time, File Return to?
 2) 19/1/22-typist
 Rep. Format: Merimen
 Lump Sum / LBL (\$) \$2750
 Days Of Repair: 3
 Resurvey No. of Trip: 1
 Add Fee: : Site Insp (\$) : Interview (\$) : Tech. Invs (\$) : Weekend (\$)
 Survey Fee: _____
 Transportation: _____
 S + RS. SI _____
 Photos _____
 Others _____
 TOTAL _____

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: Tokio Marine Insurance Singapore Ltd (HQ)
CCPL

Singapore

PARTICULARS OF CLAIM

| | | | |
|-------------------------------|--|--------------------|-------------------|
| Claim Type: | THIRD PARTY | Ref. No: | |
| Policy No: | | Date of Loss: | 28/12/2021 |
| Vehicle Reg. No.: | SHB4811U | Driveable? | YES |
| Party At Fault: | UNKNOWN | | |
| Make/Model: | TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A) | Vehicle Reg. Date: | 13/09/2017 |
| Vehicle Colour: | YELLOW | Gen Condition: | GOOD |
| Engine No: | 2ZRS061460 | Chassis No: | JTDKB3FUX03563330 |
| Odometer: | 529629 KM | | |
| Paint Type: | | | |
| List Item Discount: | 25.00 % | | |
| Total Loss? | NO | | |
| Est. Duration of Repair (day) | 4 | | |
| Present Location: | COMFORTDELGRO ENGINEERING PTE LTD (LOYANG) | | |

| COST OF CLAIMS | Amount |
|--------------------------|-----------------|
| Parts | 5,221.26 |
| Miscellaneous Items | 11.00 |
| Labour | 1,595.00 |
| Paintwork Labour | 0.00 |
| Towing | 0.00 |
| Gross Total (S\$) | 6,827.26 |
| + GST 7.00% (S\$) | 477.91 |
| Nett Amount (S\$) | 7,305.17 |

This claim is handled by: CHIANG LIAT CHOON

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Dec 2021)
Parts: 144 TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHB4811U/29/12/2021 08:39
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

| No. | Qty | Part No. | Particulars | %Disc | %Depr | Amount |
|---------------------------------------|-----|----------|-------------------------------|-------|-------|---|
| 1 | 1 | | *FRONT BUMPER | 25.00 | 0.00 | <i>M</i> *499.90 FL |
| 2 | 1 | | *FRONT BUMPER BRACKET LH/RH | 25.00 | 0.00 | <i>?</i> <i>R</i> *82.30 FL <i>LHX</i> |
| 3 | 1 | | *FRONT FENDER RH | 25.00 | 0.00 | <i>BT</i> *945.30 FL |
| 4 | 1 | | *FRONT FENDER SHIELD RH | 25.00 | 0.00 | <i>M</i> *198.50 FL |
| 5 | 1 | | *FRONT FENDER EMBLEM RH | 25.00 | 0.00 | <i>el</i> *86.50 FL |
| 6 | 1 | | *FRONT BUMPER RETAINER RH | 25.00 | 0.00 | <i>MS</i> *86.30 FL |
| 7 | 1 | | *FRONT HEAD LAMP RH | 25.00 | 0.00 | <i>cut</i> *2,735.28 FL |
| 8 | 1 | | *FRONT DAY LIGHT RH | 25.00 | 0.00 | <i>ant</i> *920.00 FL |
| 9 | 1 | | *FRONT WHEEL COVER RH | 25.00 | 0.00 | <i>ant</i> *346.40 FL |
| 10 | 1 | | *FRONT HEAD LAMP PANEL RH | 25.00 | 0.00 | <i>X</i> *240.10 FL |
| 11 | 1 | | *FRONT HEAD LAMP MOUNTING RH | 25.00 | 0.00 | <i>?</i> *25.50 FL |
| 12 | 1 | | *FRONT SUPPORT RADIATOR RH | 25.00 | 0.00 | <i>X</i> *83.50 FL |
| 13 | 1 | | *FRONT SUPPORT RADIATOR LOWER | 25.00 | 0.00 | <i>X</i> *225.40 FL |
| 14 | 1 | | *FRONT WIPER SPARE TANK ASSY | 25.00 | 0.00 | <i>X</i> *486.70 FL |
| Sub Total (S\$) | | | | | | 6,961.68 |
| - List Item Discount on L Items (S\$) | | | | | | 1,740.42 |
| Total Parts (S\$) | | | | | | 5,221.26 |

F=Franchise part. L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHB4811U/29/12/2021 08:39. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

| No | Qty | Particulars | Amount |
|----------------------------|-----|----------------------|--------------|
| Miscellaneous Items | | | |
| 1 | 1 | OD/TP Case (Insurer) | 11.00 |
| Sub Total (S\$) | | | 11.00 |

Estimates on Labour

| No | Particulars | Lab.Type | Amount |
|--------------------------------|-----------------------|----------|-----------------|
| Labour Items | | | |
| 1 | PANEL BEATING | New | 525 875.00 |
| 2 | SPRAY PAINTING | New | 500 600.00 |
| 3 | CHECK WIRING | New | 30 60.00 |
| 4 | RESET WHEEL ALIGNMENT | New | ✓ 60.00 |
| Gross Labour Cost (S\$) | | | 1,595.00 |

ComfortDelGro Engineering Pte Ltd/SHB4811U/29/12/2021 08:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

*Tanpin 72485749
 'w' 29/12/21 @ 430
 4/5 Resurvey after repair
 Tanpin & Whitford
 2-3 days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order: 4156883

JC NO:305499536


CUSTOMER
R/MS CITYCAB PTE LTD
CUSTOMER NO 7010070
ADDRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
TEL (R) 65551188 (O)
(P)
DISCOUNT CARD NO.

| | |
|-----------------------------------|----------------------------------|
| REGN NO: SHB4811U | MILEAGE |
| MAKE: TOYOTA | FUEL E.....1/2.....F |
| MODEL PRIUS HYBRID(G4) | DATE/TIME IN 28.12.2021 13:00 |
| YR OF MANU 13.09.2017 | TARGET DATE |
| CHASSIS CODE JTDKB3FUX03563330 | COMPLETION DATE/TIME: |

JOB DESCRIPTION

Accident Date: 28.12.2021
NATURE: 3P 28.12.2021

| S/NO | LABOR CODE | DESCRIPTION |
|------|------------|-------------|
|------|------------|-------------|



CHECKED & PASSED OUT BY: _____

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Acknowledgement Slip

Exit Pass

Plate No.: SHB4811U CHIANG

Vehicle No.: SHB4811U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Vehicle returned to Service Reception upon collection

To be kept by Security Guard