



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
-			Ref:	CS/TP21013288/R1vce2
LI XIAOWEN 14 CLIFTON VALE SINGAPORE 359688			Date:	05/01/2022
			Code:	TP2
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.		Veh. Inspected	SLB 1510K
	Policy No.		Coverage (\$)	0.00
	Claim No.		Excess (\$)	0.00
	Assign From		Assign Date	29/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	PEUGEOT 3008 1.2 EAT8 ACTIVE P	c.c	1199
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	VF3MRHNSUMS131835	Colour	BLUE
	Odometer	7671 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/65 R17	MICHELIN	6 mm
	L/H Front Tyre	215/65 R17	MICHELIN	6 mm
	R/H Rear Tyre	215/65 R17	MICHELIN	6 mm
	L/H Rear Tyre	215/65 R17	MICHELIN	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	24/11/2021	Inspection Date	29/12/2021
	Survey held at	AUTOFRANCE 305, ALEXANDRA ROAD SINGAPORE 159942.		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	