

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013289/UTY3N2**Date:** 07/01/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMHCSNA00004192100
Claimant Vehicle No :	FBN2382L	Insured Vehicle No :	SMX4958E
Date of Loss:	19/12/2021	Nature of Claim:	TP
		Claim No:	SNM21D207623/C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBN2382L	Engine No:	KC27E2125206
Make & Model:	HONDA FS150F, 149cc	Chassis No:	PMKKC27B0JB105617
Reg. Date:	20/08/2018 (Man. Year: 2018)	Odometer:	78634 km
Colour:	Multi-colour		
Engine Capacity:	149 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	90/80-17	Rear Tyre Size:	120/70-17
Front Left Side:	IRC 7 mm	Rear Left Side:	IRC 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,632.30	1,745.80	2,886.50	62.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	880.00	280.00	600.00	68.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	5,512.30	2,025.80	3,486.50	63.25
Approved Total (Overridden) (\$\$)		1,600.00		
Nett Amount (\$\$)	5,512.30	1,600.00	3,912.30	70.97

INSPECTION

Date of Assignment:	29/12/2021	Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ) 1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit Singapore 417883
Date Inspected:	30/12/2021 Inspected At:	
Estimated Period of Repair:	4.0 days	

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jan 2022)	
Parts:	N/A	HONDA FS150F 149cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBN2382L)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*FRONT FORK TUBE ASSY	Serviceable	680.00 FL	*- FL
2	1		*FORK UNDER BRACKET	Serviceable	220.00 FL	*- FL
3	1		*HANDLE BAR	Serviceable	88.00 FL	*- FL
4	1		*HANDLE BAR END O/S	Cut	68.00 FL	*30.00 FL
5	1		*HANDLE GRIP (SET)	Not Necessary	76.00 FL	*- FL
6	1		*BRAKE LEVER	Scratched	70.00 FL	*48.00 FL
7	1		*O/S SIDE MIRROR	Cut	120.00 FL	*75.00 FL
8	2		*SIDE FAIRING INNER COVER	Cut	280.00 FL	*280.00 FL
9	1		*CENTER COVER	N/s Cut	270.00 FL	*115.00 FL
10	1		*FAIRING ASSY (SET)	Cracked	625.00 FL	*625.00 FL
11	1		*FRONT FOOTREST BRACKET	O/s Bent	130.00 FL	*65.00 FL
12	1		*FRONT FOOTREST RUBBER	O/s Torn	110.00 FL	*40.00 FL
13	1		*BRAKE PEDAL	Cut	48.00 FL	*48.00 FL
14	1		*REAR FOOTREST	O/s Cut	98.00 FL	*46.00 FL
15	2		*REAR FOOTREST BRACKET	Not Necessary	156.00 FL	*- FL
16	1		*EXHAUST ASSY	Repair	585.00 FL	*- FL
17	1		*EXHAUST PROTECTOR	Cut	105.00 FL	*105.00 FL
18	1		*EXHAUST PROTECTOR END COVER	Cut	85.00 FL	*85.00 FL
19	1		*SIDE STAND	Not Necessary	98.00 FL	*- FL
20	1		*BASKET	Not Necessary	95.00 FL	*- FL
21	1		*NUMBER PLATE (SET)	Not Necessary	38.00 FS	*- FS
22	2		*FORK OILS	Not Necessary	30.00 FS	*- FS
23	2		*FORK OIL SEALS	Not Necessary	56.00 FS	*- FS
24	1		*STEERING CONE (SET)	Not Necessary	96.00 FS	*- FS
25	1		*REAR BOX	Cut	380.00 FS	*300.00 FS
26	1		*REAR BOX BRACKET	Not Necessary	180.00 FS	*- FS
27	1		*STICKER	Not Necessary	158.00 FS	*- FS
28	1		*IU COVER	Torn	88.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,033.00	1,902.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	400.70	156.20
Total Parts (\$\$)	4,632.30	1,745.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
2	TO PROVIDE TOWING SERVICE (LOD) (NPA)	New	0.00	0.00
3	TO REPAIR BODY FRAME	New	380.00	0.00
4	TO PROVIDE LABOUR	New	420.00	280.00
Gross Labour Cost (\$)			880.00	280.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >