

SKN333R 2020 Feb.

TPAXA
dense

BMW520i 1988cc

WBAJA12040BJ20163

Front RH Door Dented 1863 ✓

Front RH Door Lock. M M 249 X

Front RH Door Weatherstripe. M 347 ✓

Front RH Wing Mirror Rys 1623 X

Rear RH Door Rys 1942 X

Rear RH Door Lock 254 X

Rear RH Door Weatherstripe. 241 X

Rear RH Door Outer Handle. M 149 X

Sill Panel Outer Garnish Rys 695 X

Sill Panel Outer Garnish Clips. M 50(su) X

2210

1989.70

SKN3333R.

Panel Beating.

1410

~~800~~ 500
~~1000~~ 800

Spray Painting.

~~1000~~ 300

Wiring

To transfer front and rear door fittings.

~~300~~ 80

Total: 3389.00

H/S

247K

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2.7K