

ASS. REC. BY:

REF:

CS/ICS 21013298/DAY<sup>3</sup>

## ASSIGNMENT

COE March 2028

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

98

days

Res.: Yes or No

Lum Sum:

71P

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SH9943C

Yr Regn:

2020 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Hyundai Ioniq

c.c 1580

Colour:

Blue

A/C: Insured / Std / NI / NA

Sp. Reading

140351

T/Radio: Insured / Std / NI / NA

Eng/No:

G4LEKU409922

C/No:

KMHC851CVLU190248

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65 R15

R:

— 11 —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal.

S

mm

R/Bal.

S

mm

L/Bal.

S

mm

L/Bal.

S

mm

D.O.A.

25/12/2021

D.O.I.

30/12/2021

Survey held at

Bijust 8m Ming

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Front 4 Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

ECICS SSu 8213X

02/08pm Insure 71P 17,962.44 with 9 days 2 rev  
(Red. \$ 16,166.22, 47%10)

Date/Time, File Pass to?

☐

Prel. Report

1) 3/8/22

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Rep. Form:

Tp- mermen

Lump Sum / E.I.:

17962.44



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	27/12/2021 13:03 (SGT)
Date of Accident	25/12/2021 11:40 (SGT)
Exact Location of Accident	Clementi Ave 6, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SH9943C
-----------------------------	---------

#### INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Company Reg No	1XXXXX821R
Email Address	fleetsafety@cdgtaxi.com.sg
Mobile Phone No	(Phone) +65-96897481
Alternative Phone No	(Office) +65-65508768

#### VEHICLE PARTICULARS

Manufacturer	Hyundai
Model	Ae ioniq
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1580

#### INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdPartyFireTheft
Fleet Policy	Yes
Policy Number	VFX/P2419138
Cover Note Number	-

#### DRIVER

Name of Driver	TENG HUA KOON
NRIC No	SXXXX997E



Date Of Birth	11/09/1963
Occupation	Outdoor
Date Of Driving Pass	07/07/1981
Driving experience	40 YEARS AND 5 MONTHS
Gender	Male
Mobile Number	(Phone) +65-96897481
Alt. Phone Number	-
Email Address	fleetsafety@cdgtaxi.com.sg
Address	207B COMPASSVALE LANE #08-20
Address complement	-
Postcode	543207
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	3
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### PASSENGER 1

Name	UNKNOWN
Gender	Male

#### PASSENGER 2

Name	UNKNOWN
Gender	Female

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

ON 25/12/2021 AT ABOUT 11:40HRS. I WAS DRIVING VEHICLE A, SH9943C TRAVELLING ALONG CLEMENTI AVE 6 AT THE CENTER LANE. VEHICLE C MAKE A SUDDEN BRAKE. I STEPPED ONTO MY FOOTBRAKE AND I MANAGED TO STOP IN TIME. FEW MOMENTS LATER, I FELT AN IMPACT COMING FROM MY REAR AND I REALISED VEHICLE B HAS REAR ENDED MY VEHICLE AND CAUSED MY VEHICLE TO MOVE FORWARD AND REAR ENDED VEHICLE C. THIS WAS A CHAIN COLLISION ACCIDENT.

#### ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Reasons for not uploading a video of the accident	FILE IS NOT SUITABLE
Was there any audio recorded?	No

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number	SJU8213X
Vehicle Manufacturer	Toyota
Vehicle Model	Wish
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	YAP CHUN YI
Contact Number	(Phone) +65-98565899
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

**DETAILS OF OTHER VEHICLE PROPERTY 2**

Vehicle Registration Number	SFT9117L
Vehicle Manufacturer	Audi
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	TAN GEK NENG
Contact Number	(Phone) +65-98450516
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	2

Describe Circumstances of the Accident

ON 25/12/2021 AT ABOUT 11:40HRS. I WAS DRIVING VEHICLE A, SH9943C TRAVELLING ALONG CLEMENTI AVE 6 AT THE CENTER LANE. VEHICLE C MAKE A SUDDEN BRAKE. I STEPPED ONTO MY FOOTBRAKE AND I MANAGED TO STOP IN TIME. FEW MOMENTS LATER, I FELT AN IMPACT COMING FROM MY REAR AND I REALISED VEHICLE B HAS REAR ENDED MY VEHICLE AND CAUSED MY VEHICLE TO MOVE FORWARD AND REAR ENDED VEHICLE C. THIS WAS A CHAIN COLLISION ACCIDENT.

Declaration

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time 10:30 27/12/21

Witnessed by Reporting Centre Personnel M.D. (922-44)

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	821R
<b>Vehicle Details</b>	
Vehicle No.:	SH9943C
Vehicle to be Exported:	Yes
Intended Deregistration Date:	27 Dec 2021
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV FL 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2019
Engine No.:	G4LEKU409922
Chassis No.:	KMHC851CVLU190248
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,846.00
Original Registration Date:	18 Mar 2020
First Registration Date:	18 Mar 2020
Transfer Count:	0
Actual ARF Paid:	\$13,185.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	17 Mar 2028
PARF Rebate Amount:	\$9,888.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	17 Mar 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$26,566.00
COE Rebate Amount:	\$20,648.00
<b>Total Rebate Amount:</b>	<b>\$30,536.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 27 Dec 2021

OK

# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 27-Dec-21  
 MODEL: HYUNDAI IONIC  
 VEHICLE NO.: SH 9943C

30/12/2021 @ 1000hrs

Not Authorised

3/Part

8 days.

*(Signature)*

2kk And

Description	Qty	List Price	Amount
Bonnet <i>vt</i>	1	\$ 2,253.80	\$ 2,253.80
Bonnet Lock <i>src vt</i>	1	\$ 127.30	\$ 127.30
Radiator Grille NEW MODEL <i>broken</i>	1	\$ 1,568.60	\$ 1,568.60
Flap Assy Active Air Upper, (LH/RH) <i>broken</i>	2	\$ 824.60	\$ 1,649.20
Flap Assy Active wire <i>HN</i>	1	\$ 765.30	\$ 765.30
Front Number Plate garnish <i>defunct src</i>	1	\$ 188.00	\$ 188.00
Front Bumper Cover <i>distorted / broken</i>	1	\$ 418.30	\$ 418.30
Front bumper top cover <i>HN</i>	1	\$ 476.30	\$ 476.30
Front Bumper Sponge <i>turn</i>	1	\$ 186.90	\$ 186.90
Front Bumper Reinforcement <i>vt</i>	1	\$ 1,075.10	\$ 1,075.10
Front Bumper Reinforcement ABSORBER (LH/RH) <i>vt</i>	2	\$ 186.50	\$ 373.00
Front Bumper Towing Cover <i>src</i>	1	\$ 29.00	\$ 29.00
Front Bumper Moulding Centre Upper <i>mostly broken</i>	1	\$ 368.50	\$ 368.50
Front Bumper Moulding <i>HN</i>	1	\$ 93.60	\$ 93.60
Front Bumper Lower Stiffner <i>HN</i>	1	\$ 285.10	\$ 285.10
Front bumper lower grille <i>HN</i>	1	\$ 365.30	\$ 365.30
front bumper lower grille moulding <i>HN</i>	1	\$ 127.60	\$ 127.60
Front Bumper Lip <i>HN</i>	1	\$ 35.10	\$ 35.10
Front Bumper Bracket Top (LH/RH) <i>HN</i>	2	\$ 35.00	\$ 70.00
Front Bumper Bracket (LH/RH) <i>src</i>	2	\$ 28.00	\$ 56.00
Front Bumper Retainer Mounting (LH/RH) <i>HN</i>	2	\$ 65.30	\$ 130.60
Front Bumper Clips 10 pcs <i>HN</i>	1	\$ 25.00	\$ 25.00
Headlamp Support Panel Assy <i>mostly broken</i>	1	\$ 949.30	\$ 949.30
Headlamp(LH/RH) <i>crack 2110.30 x 2</i>	2	\$ 3,987.30	\$ 7,974.60
Horn Unit (LH/RH) <i>HN</i>	2	\$ 72.80	\$ 145.60
Horn Wire <i>HN</i>	1	\$ 386.70	\$ 386.70
Radiator Inverter <i>vt</i>	1	\$ 884.80	\$ 884.80
Radiator <i>vt</i>	1	\$ 710.50	\$ 710.50
Radiator fan blower motor assy <i>crack / broken</i>	1	\$ 1,226.60	\$ 1,226.60
Radiator Air Guard (LH/RH) <i>src</i>	2	\$ 76.40	\$ 152.80
Radiator Air Guard, Upr (LH/RH) <i>src</i>	2	\$ 127.50	\$ 255.00
Aircon Condenser <i>vt</i>	1	\$ 663.60	\$ 663.60
Boot Lid <i>HN</i>	1	\$ 2,480.40	\$ 2,480.40
Boot Lid Rubber <i>HN</i>	1	\$ 187.40	\$ 187.40
Boot Lid 'H' Emblem <i>HN</i>	1	\$ 28.00	\$ 28.00
Emblem-Hybrid <i>HN</i>	1	\$ 24.30	\$ 24.30
Emblem-Ioniq <i>HN</i>	1	\$ 31.30	\$ 31.30
Boot Lid Trimboard <i>HN</i>	1	\$ 259.70	\$ 259.70
Boot Lid Trimboard Clips (10pcs) <i>HN</i>	1	\$ 11.00	\$ 11.00
Boot Lid Trimboard, Centre <i>HN</i>	1	\$ 159.60	\$ 159.60
Boot Lid Glass Upper Moulding <i>HN</i>	1	\$ 186.30	\$ 186.30
Boot Lid Glass Lower Moulding <i>HN</i>	1	\$ 145.20	\$ 145.20
Rear Bumper <i>distorted / mostly crack</i>	1	\$ 459.40	\$ 459.40

394.80

4220.60



Rear Bumper Reinforcement <i>CRACK</i>	1	\$ 394.80	\$ 394.80	✓
Rear Bumper Reinforcement Bracket (LH/RH) <i>1st</i>	2	\$ 188.10	\$ 376.20	✓
Antenna Assy-SMARTK outer <i>missing broken</i>	1	\$ 689.50	\$ 689.50	✓ 40.50
Rear Bumper Centre Moulding Assy <i>broken</i>	1	\$ 451.25	\$ 451.25	✓
Rear Bumper Lower Centre Moulding Assy <i>SVL</i>	1	\$ 47.50	\$ 47.50	X
Rear Bumper Stay <i>HH</i>	1	\$ 138.10	\$ 138.10	X
Rear Bumper Side retainer (LH/RH) <i>SVL</i>	2	\$ <del>85.80</del>	\$ 171.60	X
Rear Bumper Cover Clips <i>hlc</i>	1	\$ 22.00	\$ 22.00	✓
Rear Bumper Under Centre <i>HH missing broken</i>	1	\$ 123.85	\$ 123.85	✓
Rear Bumper Side Under(LH/RH) <i>HH</i>	2	\$ 123.10	\$ 246.20	Y
Rear Bumper Rear Hook <i>HH</i>	1	\$ 94.60	\$ 94.60	X
Rear Bumper Reflector Lamp(LH/RH) <i>o/s custodial</i>	2	\$ <del>82.90</del>	\$ 165.80	✓
Rear Bumper Towing Cover <i>SVL</i> <i>HS HH</i>	1	\$ 98.80	\$ 98.80	X
Rear Bumper Reserve Light (Parking Brake Light) <i>scrut</i>	1	\$ 328.60	\$ 328.60	✓
Licence Lamp <i>HH</i> <i>broken</i>	1	\$ 193.53	\$ 193.53	X
Rear Panel <i>Debit</i>	1	\$ 532.00	\$ 532.00	✓
Rear Panel Garnish <i>HH</i>	1	\$ 346.80	\$ 346.80	X
Rear tray tools box RH <i>HH</i>	1	\$ 675.30	\$ 675.30	X 19019.70
Rear tray tools box LH <i>HH</i>	1	\$ 693.20	\$ 693.20	X
REAR TRAY LUGGS CENTER <i>HH</i>	1	\$ 354.20	\$ 354.20	X 15215.76
Exhaust Silencer <i>HH</i>	1	\$ 943.50	\$ 943.50	X
Exhaust Pipe Hanger <i>HH</i>	1	\$ 29.20	\$ 29.20	X

SUB TOTAL \$ 35,106.23

LESS 20% \$ 7,021.25

DISCOUNTED TOTAL \$ 28,084.98

Front

Front Number Plate <i>SVL cut</i> SN	1	\$ 25.00	\$ 25.00	X } 45/-
Front No Plate Trim Cover <i>SVL cut</i> SN	1	\$ 30.00	\$ 30.00	X
COOLANT <i>HH</i> SN	1	\$ 45.00	\$ 45.00	X
INVERTER COOLANT <i>HH</i> SN	1	\$ 65.00	\$ 65.00	X
Boot Lid Comfort Logo & Tel No. Sticker <i>HH</i> SN	1	\$ 35.00	\$ 35.00	X
Boot Lid Comfort Cablink Tel No. Sticker <i>HH</i> SN	1	\$ 30.00	\$ 30.00	X 275.00
Rear Windscreen Sealant <i>HH</i> SN	2	\$ 46.00	\$ 92.00	X
Rear Bumper Rubber Mat <i>hlc</i> SN	1	\$ 50.00	\$ 50.00	✓
Rear Bumper Reverse Sensor <i>Down</i> SN	1	\$ 180.00	\$ 180.00	✓

SUB TOTAL \$ 552.00

#### Labour Charge

Panel Beating	1	\$1,800.00	\$1,800.00	1000/-
Spray Painting Charge	1	\$1,800.00	\$1,800.00	800/-
Wiring Charge	1	\$100.00	\$100.00	30/-
Tuff Kote	1	\$100.00	\$100.00	40/- 2190.00
Towing Charge	1	\$80.00	\$80.00	HH
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00	HH
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00	40/-
Remove/Refix Exhaust Pipe	1	\$80.00	\$80.00	HH
Remove/Refix Radiator	1	\$90.00	\$90.00	50/-
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00	80/-
Remove/Refix Fuse Box	1	\$120.00	\$120.00	HH
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	150/-

TOTAL LABOUR \$5,210.00

ESTIMATE TOTAL \$ 33,846.98

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance



# BIFROST AUTO PTE LTD

## REPAIR ESTIMATE

DATE: 30-Dec-21

INSURANCE: \_\_\_\_\_

MODEL: HYUNDAI IONIC

VEHICLE NO.: SH 9943C

Description	Qty	List Price	Amount
Aircon metal hose - small <i>Denbu</i>	1	\$ 352.10	\$ 352.10
<b>SUB TOTAL</b>			<b>\$ 352.10</b>
<b>LESS 20%</b>			<b>\$ 70.42</b>
<b>DISCOUNTED TOTAL</b>			<b>\$ 281.68</b>
<b>ESTIMATE TOTAL</b>			<b>\$ 281.68</b>

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

*Tanya*

*LKK And*

*8*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

*17680.76*

*Sup 281.68*

*PIP 17,962.44*

*9 & days.*

*34128.66*