

AXA Ins. Spine Road.
8 Shenton Way
27-01 AXA Tower
Spine 068811

Date: 23/10/21

Attn.: Motor Claims Department

Dear Sir/Madam

RE: Accident involving vehicles FBK 6831 K & SEC 8909 K
On 21/10/21 at Marsling Dr.

It is in my opinion that the above mentioned accident was caused solely by the negligence of the driver of the vehicle no: SEC 8909 K

As the above vehicle was insured by your insurance company at the material time of the accident. I would appreciate that you could kindly arrange your surveyor to survey my vehicle soonest possible at the following address :-

Kan Fook Sing Motor Workshop
61 Defu Lane 12
Singapore 539147
Tel : 67479560 (O)

Thank you

Yours faithfully

A large, stylized handwritten signature in black ink, consisting of a large loop and a smaller loop, with a wavy line above it.



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD

DATE : 23-10-2021

8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

VEHICLE NO. : FBR6831K

ACCIDENT DATE : 21-10-2021 06:45

THIRD PARTY REF. : SHC8909R

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEHICLE FBR6831K YAMAHA AEROX GDR155A CVT ABS

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	1	COVER SET	680.00
2	1	FOOTREST (RH)	58.00
3	1	BOX BRACKET	320.00
4	1	MUFFLE PROETCTOR	95.00
5	1	CENTRE COMPARTMENT	288.00
6	1	HEAD LAMP ASSY	305.00
7	1	LOWER PANNER (LH)	75.00
8	1	AIR FILTER BOX	85.00
9	1	CLUCTH COVER (BIG)	105.00
10	1	TOP PANNER	185.00
11	1	FRONT FORK	580.00
12	1	UNDER BRACKET	145.00
13	1	STEEIRNG CONE & BEARING	95.00
14	1	FRONT BRAKE DISC	95.00
15	1	BODY JOINT	85.00
16	2	FRONT SIGNAL LAMPO @\$45.00	90.00
			3,286.00
			LESS 5 %
			164.30
			TOTAL (A)
			3,121.70

LABOUR CHARGES

1	1	TO CHECK WHEEL ALIGNMENT	80.00
2	1	TO PRESS FORK ASSY	250.00



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147

Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428

E-mail: ryan@kanfs.net/ patricia@kanfs.net

Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883

Tel: (65) 6481 5150 Fax: (65) 6481 8683

VEHICLE NO. : FBR6831K
ACCIDENT DATE : 21-10-2021 06:45
THIRD PARTY REF. : SHC8909R

#	QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
3	1	REMOVE ALL NECESSARY AFFECTED PARTS FOR REPAIRS, WELD/CUT, PANEL BE- ATING & RENEW PARTS	300.00
4	1	SPRAY PAINTING	300.00
TOTAL (D)			930.00
ESTIMATE TOTAL			4,051.70