3/29/22, 11:34 AM Adjuster Report

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21013302/UQY3N2

29/03/2022 Date:

REFERENCE

China Taiping Insurance Handling Insurer:

(Singapore) Pte. Ltd.

Policy No:

DMPCSNW00225122106

Claimant Vehicle No:

JUR1915

Insured Vehicle No:

SJL1915Y

Date of Loss:

24/12/2021

Nature of Claim: TP

Engine No:

Chassis No:

Odometer:

SNM21D207578/C02/TANKW

PMKJC8060LB123385

JC80E2139525

8254 km

DESCRIPTION & IDENTIFICATION OF VEHICLE

JUR1915 Reg No:

Make & Model: HONDA DASH 125, 125cc

Reg. Date: 11/06/2021 (Man. Year: 2021)

Colour: Black

Engine Capacity: 125 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Engine Modification: Pre-accident Condition: Yes Nο

CONDITION OF TYRES

Front Tyre Size: 70/90-17 Rear Tyre Size: 80/90-17 Front Left Side: Rear Left Side: Dunlop 6 mm Dunlop 6 mm

Front Right Side: Rear Right Side: 0 mm 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	994.00	774.00	220.00	22.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	780.00	610.00	170.00	21.79
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S	1,774.00	1,384.00	390.00	21.98
Approved Total (Overridden) (S	5\$)	1,100.00		
(\$	1,774.00	1,100.00	674.00	37.99
+ GST 7.00/7.00% (S	5\$) 124.18	77.00	47.18	37.99
Nett Amount (S	1,898.18	1,177.00	721.18	37.99

INSPECTION

Date of Assignment: 23/03/2022

Precise Auto Service (HQ) 30/12/2021 Inspected At: Date Inspected:

No 1 Kaki Bukit Ave 6, #02-34/36

Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 28 Mar 2022)

Parts: N/A HONDA DASH 125 125cc (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for JUR1915)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

 		*STEERING HANDLE BAR	Bent	95.00 FL	*05.00.51
<u> </u> 				95.00 FL	*95.00 FL
		*STEERING BALANCER	Cut	28.00 FL	*28.00 FL
		*STEERING HANDLE RUBBER GRIP	Cut	85.00 FL	*85.00 FL
		*MIRROR SET	Cut	58.00 FL	*58.00 FL
		*RIDER FOOT REST BAR	Bent	60.00 FL	*60.00 FL
		*RIDER FOOT REST RUBBER	Torn	28.00 FL	*28.00 FL
		*REAR FOOT REST	Cut	28.00 FL	*28.00 FL
		*REAR SIGNAL LAMP SET	Cracked	58.00 FL	*58.00 FL
		*PILLION HAND GRIP BRACKET SET	Cut	85.00 FL	*85.00 FL
		*BODY FAIRING SET	Cracked	245.00 FL	*245.00 FL
		*FERRING STICKER SET	Necessary	90.00 FL	*90.00 FL
		*HELMET	Repair	220.00 FS	*- FS
hise p	art. S=SpcNe	tt. L=ListItemDisc.	_		
			Sub Total (S\$)	1,080.00	860.00
		- List Item Discount on L Ite	ms 10.00/10.00% (S\$)	86.00	86.00
			Total Parts (S\$)	994.00	774.00
	nise p	nise part. S=SpcNe	*RIDER FOOT REST BAR *RIDER FOOT REST RUBBER *REAR FOOT REST *REAR SIGNAL LAMP SET *PILLION HAND GRIP BRACKET SET *BODY FAIRING SET *FERRING STICKER SET *HELMET nise part. S=SpcNett. L=ListItemDisc.	*RIDER FOOT REST BAR *RIDER FOOT REST RUBBER Torn *REAR FOOT REST Cut *REAR SIGNAL LAMP SET Cracked *PILLION HAND GRIP BRACKET SET *BODY FAIRING SET Cracked *FERRING STICKER SET Necessary *HELMET Repair sise part. S=SpcNett. L=ListItemDisc. Sub Total (S\$) - List Item Discount on L Items 10.00/10.00% (S\$)	*RIDER FOOT REST BAR

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO REPLACE RECOMMENDED PARTS	New	380.00	280.00
2	TRANSPORT CHARGES (2 TRIPS)	New	100.00	50.00
3	RESPRAY	New	300.00	280.00
		Gross Labour Cost (S\$)	780.00	610.00
	Report was	unsubmitted during this print-out.		

< END OF ESTIMATES >