

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI21013303/UVY3Q2**Date:** 19/04/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNW00067812100

Claimant Vehicle No : SLR4369Z **Insured Vehicle No :** GBK3697M

Date of Loss: 27/12/2021 Nature of Claim: TP Claim No: SNM21D207628/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR4369Z**

Make & Model: HYUNDAI ELANTRA, 1.6 AD GLS (A) Engine No: G4FGHU687069

Reg. Date: 16/08/2017 (Man. Year: 2017) Chassis No: KMHD841CMJU527907

Colour: Black Odometer: 128169 km

Engine Capacity: 1591 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Yokohama 7 mm Rear Left Side: Yokohama 7 mm

Front Right Side: Yokohama 7 mm Rear Right Side: Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,406.00	2,886.40	3,519.60	54.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,760.00	1,120.00	640.00	36.36
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	8,166.00	4,006.40	4,159.60	50.94
Approved Total (Overridden) (\$\$)		3,200.00		
(\$\$)	8,166.00	3,200.00	4,966.00	60.81
+ GST 7.00/7.00% (\$\$)	571.62	224.00	347.62	60.81
Nett Amount (\$\$)	8,737.62	3,424.00	5,313.62	60.81

INSPECTION

Date of Assignment: 30/03/2022

Date Inspected: 30/12/2021 Inspected At: Stytech Auto Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #02-30, Kaki Bukit Autohub
Singapore 417921

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Apr 2022)

Parts: 143 HYUNDAI ELANTRA 1.6 AD GLS (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLR4369Z)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LEFT HEADLAMP	Scratched	1,198.00 F	*1,198.00 FL
2	1		*FRONT BUMPER	Repair	489.00 F	*- FL
3	1		*FRONT BUMPER CLIPS	Necessary	30.00 FS	*30.00 FS
4	1		*FRONT BUMPER RETAINER (LEFT)	Not Necessary	39.00 F	*- FL
5	1		*FRONT FENDER (LEFT)	Repair	1,227.00 F	*- FL
6	1		*FRONT LEFT DOOR	Warped / Bent	1,904.00 F	*1,904.00 FL
7	1		*FRONT LEFT DOOR FRAME STICKER	Necessary	31.00 F	*31.00 FL
8	1		*FRONT LEFT DOOR CHROME HANDLE	Not Necessary	179.00 F	*- FL
9	1		*LEFT SIDE MIRROR	Repair	638.00 F	*- FL
10	1		*FRONT LEFT SPORT RIM	Cut	671.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,406.00	3,513.00
- List Item Discount on L Items 0.00/20.00% (\$\$)	0.00	626.60
Total Parts (\$\$)	6,406.00	2,886.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TRANSFER DOOR MECHANISM	New	120.00	60.00
2	CHECK WIRING	New	60.00	20.00
3	ANTI RUST PROOF	New	80.00	40.00
4	PANEL BEATING	New	600.00	400.00
5	TO PUTTY & SPRAY PAINTING	New	900.00	600.00
Gross Labour Cost (\$)			1,760.00	1,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >