

Vehicle No. : SHA8004L  
Make : HYUNDAI  
Model : IONIQ(G3)

Insurance: China Taiping  
MVA: MS. LOKE YY

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	FRT DOOR OUTER HANDLE RH			<i>dis</i> \$234.80
1	RR DOOR OUTER HANDLE RH			<i>dis</i> \$108.40
	SUB TOTAL			\$343.20
	LESS 20%			\$68.64
	DISCOUNTED TOTAL		274.56	\$274.56
	RR DOOR COMFORTDELGRO LOGO STICKER RH			<i>new</i> \$80.00
	FRT DOOR COMFORTDELGRO LOGO STICKER RH			<i>new</i> \$75.00
			155	\$155.00
	Labour Charge			350
	PANEL BEATING			\$700.00
	SPRAY PAINTING CHARGE		850	500 \$600.00
	CHECK WIRING		M	X \$60.00
	TOTAL LABOUR			\$1,360.00
	ESTIMATE TOTAL		\$1279.56 + 2 days *	\$1,789.56

is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Tauphin 92495749

wp 27/12/21 e, 450.

9/1 Resay after new parts, higher points

2 Aug

Samir Khanloum

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company