

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 27-Dec-21INSURANCE: CHINA TAIPINGMODEL: Hyundai IoniqMVA: LIM T SVEHICLE NO.: SHD7219A

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Rear Door LH	1		\$1,789.90 <i>Rp</i>
	Rear Door Protector LH	1		\$166.20 <i>cut</i>
	Rear Wheel Cap LH	1		\$346.40 <i>cut</i>
	Rocker Panel Garnish LH	1		\$290.00 <i>Rp</i>
	SUB TOTAL		512.60	\$2,592.50
	LESS 20%			\$590.50
	DISCOUNTED TOTAL		410.08	\$2,362.00
	Rear Door APPS LH	1		\$80.00 <i>at</i>
	Rear Fender (Petrol Only) LH	1		\$40.00 <i>at</i>
			120	
	S/NETT TOTAL			\$120.00
	SPARE PARTS TOTAL			\$2,482.00
	Labour Charge			
	Panel Beating – Rear Fender LH			\$800.00 <i>525</i>
	Spray Painting Charge – Rear Bumper Etc			\$1,200.00 <i>850</i>
	Tuff Kote		1375	\$60.00 <i>x un</i>
	Transfer Of Doors			\$240.00 <i>x un</i>
	TOTAL LABOUR		1405.08	\$2,300.00
	ESTIMATE TOTAL		4541500	\$4,782.00
			2 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 92475249

WP'

27/10/21 @ 405

L/S Rising after repair

Tanpin 92475249

(2) 3 days