

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE: 27-Dec-21MODEL: Hyundai IoniqVEHICLE NO.: SHD7219AINSURANCE: CHINA TAIPINGMVA: LIM T S

| PART NO. | DESCRIPTION                             | QTY | UNIT PRICE | AMOUNT                |
|----------|-----------------------------------------|-----|------------|-----------------------|
|          | Rear Door LH                            | 1   |            | \$1,789.90 <i>Rp</i>  |
|          | Rear Door Protector LH                  | 1   |            | \$166.20 <i>cut</i>   |
|          | Rear Wheel Cap LH                       | 1   |            | \$346.40 <i>not</i>   |
|          | Rocker Panel Garnish LH                 | 1   |            | \$290.00 <i>Rp</i>    |
|          | <b>SUB TOTAL</b>                        |     |            | \$2,592.50            |
|          | <b>LESS 20%</b>                         |     |            | \$590.50              |
|          | <b>DISCOUNTED TOTAL</b>                 |     |            | <b>\$2,362.00</b>     |
|          | Rear Door APPS LH                       | 1   |            | \$80.00 <i>at</i>     |
|          | Rear Fender (Petrol Only) LH            | 1   |            | \$40.00 <i>not</i>    |
|          | <b>S/NETT TOTAL</b>                     |     |            | <b>\$120.00</b>       |
|          | <b>SPARE PARTS TOTAL</b>                |     |            | <b>\$2,482.00</b>     |
|          | <b>Labour Charge</b>                    |     |            |                       |
|          | Panel Beating – Rear Fender LH          |     |            | \$800.00 <i>525</i>   |
|          | Spray Painting Charge – Rear Bumper Etc |     |            | \$1,200.00 <i>850</i> |
|          | Tuff Kote                               |     |            | \$60.00 <i>x</i>      |
|          | Transfer Of Doors                       |     |            | \$240.00 <i>x</i>     |
|          | <b>TOTAL LABOUR</b>                     |     |            | <b>\$2,300.00</b>     |
|          | <b>ESTIMATE TOTAL</b>                   |     |            | <b>\$4,782.00</b>     |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphie 92475249

WP

27/12/21 @ 455

C/S rising after repair

Tanphie @ Wharfedale

2-3 days

\* Back on Monday, 27-12-2021  
for repair \*

Janet Lim

# COMFORTDELGRO ENGINEERING

## ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701  
Mainline : 65 6380 6280 Facsimile : 65 6280 9755  
Workshops  
205 Braddell Road Singapore 579701  
58 Loyang Drive Singapore 508909  
383 Sin Ming Drive Singapore 575717

Date/Time: 27.12.2021 13:46 Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4155820

JC NO305499212

STOMER

COMFORT TRANSPORTATION PTE LTD  
7010045  
STOMER NO.  
383 SIN MING DRIVE  
DRESS  
Singapore SINGAPORE 575717  
65508755 (O)

REGN NO.

SHD7219A

MILEAGE

MAKE

HYUNDAI

FUEL

E.....1/2.....F

MODEL

IONIQ(G2)

DATE/TIME IN

27.12.2021 11:00

YR OF MANU.

22.11.2018

TARGET DATE

CHASSIS CODE

KMHC851CVKU115276

COMPLETION DATE/TIME:

COUNT CARD NO.

### JOB DESCRIPTION

Ident Date: 23.12.2021  
RE: 3P 23.12.2021


LKK-

LS  
China

SMY  
3576A

LABOR CODE  
PB

DESCRIPTION  
PANEL BEATING-SHD7219A



CKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Wedge Slip

Exit Pass

No.: SHD7219A

LIMITS

Vehicle No.:

SHD7219A

of Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

Take back to Service Advisor