



Case Details

Case Reference Number : TAX/12/21/2044
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHD6123Z

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-17012-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 18/12/2021 06:00 AM
 Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			COVER, RR BUMPER ASSY	1	485.60	485.60	25.00	364.20	Replace	1	364.20	Replace	✓
One Time Key In	Main			REAR BUMPER REINFORCEMENT	1	332.70	332.70	25.00	249.52	Replace	0	0	Check	?
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 3	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	✓
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 2	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	✓
One Time Key In	Main			PAD, RR BUMPER, RH & LH, 1	2	4.00	8.00	25.00	6.00	Replace	2	6.00	Replace	✓
One Time Key In	Main			PAD, RR BUMPER, CTR	3	11.00	33.00	25.00	24.75	Replace	3	24.75	Replace	✓
One Time Key In	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.30	22.60	25.00	16.95	Replace	2	16.95	Replace	✓
One Time Key In	Main			RETAINER, RR BUMPER, RH	1	132.60	132.60	25.00	99.45	Replace	0	0	Not Give	X ✓
One Time Key In	Main			CLIPS PIECE, FRT & RR BUMPER	10	4.50	45.00	25.00	33.75	Replace	10	33.75	Replace	✓

Total Spare Part Cost 6,156.62

Surveyor Total 749.03

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,156.62

Final Sur Total 749.03

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			GUARD, RR BUMPER, LOWER	1	374.50	374.50	25.00	280.88	Replace	1	280.88	Replace	✓ cut
One Time Key In	Main			COVER, GUARD RR BUMPER LOWER	1	22.00	22.00	25.00	16.50	Replace	0	0	Not Give	✓ X
One Time Key In	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, RH	1	39.00	39.00	25.00	29.25	Replace	0	0	Not Give	✓ X
One Time Key In	Main			REAR BUMPER REFLECTOR ASSY, REFLEX, LH	1	39.00	39.00	25.00	29.25	Replace	0	0	Check	✓ ?
One Time Key In	Main			COVER, REAR FLOOR UNDER, RH	1	175.10	175.10	25.00	131.32	Replace	0	0	Not Give	✓ X
One Time Key In	Main			COVER, REAR FLOOR UNDER, LH	1	241.90	241.90	25.00	181.43	Replace	0	0	Not Give	✓ X
One Time Key In	Main			COVER, REAR FLOOR UNDER CENTER	1	229.90	229.90	25.00	172.43	Replace	0	0	Not Give	✓ X
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	339.60	339.60	10.00	305.64	Replace	0	0	Not Give	✓ X
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	339.60	339.60	10.00	305.64	Replace	0	0	Not Give	✓ X
One Time Key In	Main			COVER, REAR COMBINATION LAMP, RH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	✓ X
One Time Key In	Main			COVER, REAR COMBINATION LAMP, LH	1	69.90	69.90	25.00	52.43	Replace	0	0	Not Give	✓ X
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, NO.2 RH	1	261.00	261.00	10.00	234.90	Replace	0	0	Not Give	✓ X
One Time Key In	Main			LENS & BODY, REAR COMBINATION LAMP, NO.2 LH	1	261.00	261.00	10.00	234.90	Replace	0	0	Not Give	✓ X
One Time Key In	Main			LAMP ASSY, REAR, RH	1	293.60	293.60	10.00	264.24	Replace	0	0	Not Give	✓ X
One Time Key In	Main			LAMP ASSY, REAR, LH	1	293.60	293.60	10.00	264.24	Replace	0	0	Not Give	✓ X

Total Spare Part Cost 6,156.62

Surveyor Total 749.03

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,156.62

Final Sur Total 749.03

SMRT Recommendation										Surveyor Approval				
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Check	?
One Time Key In	Main			ANTENNA, ELECTRICAL KEY	1	72.00	72.00	10.00	64.80	Replace	0	0	Check	?
One Time Key In	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	651.00	651.00	25.00	488.25	Replace	0	0	Not Give	X
One Time Key In	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	X
One Time Key In	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	913.60	913.60	25.00	685.20	Replace	0	0	Not Give	X
One Time Key In	Main			EMBLEM SUB-ASSY REAR	1	47.90	47.90	25.00	35.92	Replace	0	0	Not Give	X
One Time Key In	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	54.60	54.60	25.00	40.95	Replace	0	0	Not Give	X
One Time Key In	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	54.60	54.60	25.00	40.95	Replace	0	0	Not Give	X
One Time Key In	Main			STRIDES LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0	Not Give	X
One Time Key In	Main			STICKER DECAL 65558888	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	X
One Time Key In	Main			SPOILER SUB-ASSY, REAR	1	1,575.40	1,575.40	25.00	1,181.55	Replace	0	0	Not Give	X

Total Spare Part Cost 6,156.62

Surveyor Total 749.03

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 6,156.62

Final Sur Total 749.03

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	676.00	200	
Total:			676.00	200.00	

Spray Cost Detail

12/1, 10:39

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	X
3	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	0	X
4	Main	TO RESPRAY REAR SPOILER	180.00	0	X
5	Main	TO RESPRAY REAR PANEL	180.00	0	X
Total:			1,098.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30	/
2	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	X
3	Main	TO REPLACE SUNDRY PARTS	100.00	0	X
4	Main	TO WASH AND VACUUM	60.00	0	X
5	Main	TOWING CHARGE	56.00	0	X
Total:			416.00	30.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,156.62	749.03
Total Labour Cost	676.00	200.00
Total Spray Painting	1,098.00	200.00
Other	416.00	30.00
Overall Total	8,346.62	1,179.03
Lump Sum Repair Option		☐
Lump Sum Total	8,350.00	1,179.03
Surveyor Approved Amount		1,179.03
No of Repair Days*	6	2 /

Estimator Assessment(\$)

Surveyor Assessment(\$)

Remarks

PART BY PART REPAIR / BEFORE PAINT PHOTO .

Surveyor Name

GuoQiang

Signature



Save

Clear

Survey Date

23/12/2021

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**