

**STRIDES Accident Vehicle Repair Estimates**

|                                                   |
|---------------------------------------------------|
| <b>STRIDES Automotive Services Pte Ltd</b>        |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 03/01/2022

User ID                      PohSuan

**Section A - Accident Details**

|                                    |                          |
|------------------------------------|--------------------------|
| Registration Number                | SHD6123Z                 |
| Case Reference Number              | TAX/12/21/2044           |
| Registration Date                  | 26/12/2019               |
| Company Type                       | Strides Taxi Pte Ltd     |
| Make                               | TOYOTA                   |
| Model                              | PRIUS4FL                 |
| Name of Driver                     | TAN YEW HUAT             |
| Type of Accident                   | Head to Rear             |
| Accident Date and Time             | 18/12/2021 2:00 PM       |
| Accident Reported Date and Time    | 20/12/2021 9:10 AM       |
| Is Surveyor Required?              | Yes                      |
| Survey by                          |                          |
| Vehicle is Towed Back?             | No                       |
| Towed Back Date and Time           |                          |
| Replacement Vehicle issued?        | No                       |
| Job Card Number                    | 24113444                 |
| Special Instruction to ARC, if any | TP / REAR PORTION /TOWED |
| Prepared Date and Time             | 22/12/2021 5:49 PM       |
| Chassis Number                     |                          |
| Mileage                            |                          |
| Work Shop                          |                          |
| Repair Completion Date and Time    |                          |

**Section B - Summary of Repair Estimates**

| Summary of Repair Estimates  |                                                                                     |                                                                                     |
|------------------------------|-------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------|
|                              | Quotation from ARC                                                                  | Adjusted by Surveyor, if applicable                                                 |
| Total Labour Cost            | \$676.00                                                                            | \$200.00                                                                            |
| Total Spray Cost             | \$1,098.00                                                                          | \$200.00                                                                            |
| Total Spare Part Cost        | \$6,156.62                                                                          | \$749.03                                                                            |
| Total Other Cost             | \$416.00                                                                            | \$30.00                                                                             |
| <b>TOTAL COST</b>            | <b>\$8,346.62</b>                                                                   | <b>\$1,179.03 (P/P)</b>                                                             |
| <b>Lump Sum Total</b>        | <b>\$0.00</b>                                                                       | <b>\$0.00</b>                                                                       |
| Number of Repair Days        | 6.0                                                                                 | 2.0                                                                                 |
| Prepared / Adjusted By       | <b>Ang Bang Kien</b>                                                                | <b>GUO QIANG (LKK) / AIG</b>                                                        |
| ARC / Surveyor Sign Off Date | <b>22/12/2021 6:07 PM</b>                                                           | <b>23/12/2021 4:39 PM</b>                                                           |
| Signature                    |  |  |
| Remarks                      |                                                                                     | PART BY PART REPAIR / BEFORE PAINT PHOTO .                                          |

**Section C - Quotation and Accident Invoice Details**

|                         |              |                       |  |
|-------------------------|--------------|-----------------------|--|
| <b>Quotation Number</b> | QN-2201-0007 | <b>Invoice Number</b> |  |
| <b>Quotation Date</b>   | 05.01.2022   | <b>Invoice Date</b>   |  |
| <b>Invoice Amount</b>   |              | <b>Prepared Date</b>  |  |

**Section D - Details of Repair Estimates**

**Part 1 - Labour Works**

| Job Scope              | Quotation from AR | Adjusted by Surveyor, if applicable |
|------------------------|-------------------|-------------------------------------|
| TO REPAIR REAR PORTION | \$676.00          | \$200.00                            |
| <b>Total Labour</b>    | <b>\$676.00</b>   | <b>\$200.00</b>                     |

**Part 2 - Spray Painting & Panel Beating Related Works**

| Job Scope                                       | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-------------------------------------------------|--------------------|-------------------------------------|
| TO RESPRAY REAR BUMPER                          | \$378.00           | \$200.00 ✓                          |
| TO RESPRAY BUMPER BEAM                          | \$180.00           | \$0.00 NN                           |
| TO RESPRAY TAILGATE OUTSIDE GARNISH             | \$180.00           | \$0.00 NN                           |
| TO RESPRAY REAR SPOILER                         | \$180.00           | \$0.00 NN                           |
| TO RESPRAY REAR PANEL                           | \$180.00           | \$0.00 NN                           |
| <b>Total Spray Painting &amp; Panel Beating</b> | <b>\$1,098.00</b>  | <b>\$200.00 NN</b>                  |

**Part 3 - Other Costs - Accident and Accident Repair Related Expense**

| Job Scope                               | Quotation from ARC | Adjusted by Surveyor, if applicable |
|-----------------------------------------|--------------------|-------------------------------------|
| TO TEST AND REFIX REVERSE SENSOR SYSTEM | \$120.00           | \$30.00 ✓                           |
| TO CHECK WIRING AND SYSTEM FUNCTION     | \$80.00            | \$0.00 NN                           |
| TO REPLACE SUNDRY PARTS                 | \$100.00           | \$0.00 NN                           |
| TO WASH AND VACUUM                      | \$60.00            | \$0.00 NN                           |
| TOWING CHARGE                           | \$56.00            | \$0.00 NN                           |
| <b>Total Other Costs</b>                | <b>\$416.00</b>    | <b>\$30.00</b>                      |

**Part 4 - Spare Parts / Material Usage**

| Part Number | Portion | Stock Number | Part Name                              | Quantity | List Price (\$) | Discount (%) | Final Price (\$) | Estimator Approved | Surveyor Approved |
|-------------|---------|--------------|----------------------------------------|----------|-----------------|--------------|------------------|--------------------|-------------------|
|             |         | 52159-47927  | COVER, RR BUMPER ASSY                  | 1.00     | \$485.60        | 25.00        | \$364.20         | Replace            | Replace           |
|             |         | 52023-47030  | REAR BUMPER REINFORCEMENT              | 0.00     | \$332.70        | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 52462-47130  | PAD, RR BUMPER, RH & LH , 3            | 2.00     | \$11.00         | 25.00        | \$16.50          | Replace            | Replace           |
|             |         | 52462-47030  | PAD, RR BUMPER, RH & LH , 2            | 2.00     | \$4.00          | 25.00        | \$6.00           | Replace            | Replace           |
|             |         | 52462-47020  | PAD, RR BUMPER, RH & LH , 1            | 2.00     | \$4.00          | 25.00        | \$6.00           | Replace            | Replace           |
|             |         | 52461-47070  | PAD, RR BUMPER, CTR                    | 3.00     | \$11.00         | 25.00        | \$24.75          | Replace            | Replace           |
|             |         | 52191-47030  | SEAL, RR BUMPER ARM, RH & LH           | 2.00     | \$11.30         | 25.00        | \$16.95          | Replace            | Replace           |
|             |         | 52575-47060  | RETAINER, RR BUMPER, RH                | 0.00     | \$132.60        | 0.00         | \$0.00           | Replace            | Not Given         |
|             |         | 52161-16010  | CLIPS PIECE, FRT & RR BUMPER           | 10.00    | \$4.50          | 25.00        | \$33.75          | Replace            | Replace           |
|             |         | 52453-47900  | GUARD, RR BUMPER, LOWER                | 1.00     | \$374.50        | 25.00        | \$280.88         | Replace            | Replace           |
|             |         | 52169-47070  | COVER, GUARD RR BUMPER LOWER           | 0.00     | \$22.00         | 0.00         | \$0.00           | Replace            | Not Given         |
|             |         | 81910-47030  | REAR BUMPER REFLECTOR ASSY, REFLEX, RH | 0.00     | \$39.00         | 0.00         | \$0.00           | Replace            | Not Given         |
|             |         | 81920-47030  | REAR BUMPER REFLECTOR ASSY, REFLEX, LH | 0.00     | \$39.00         | 0.00         | \$0.00           | Replace            | Check             |
|             |         | 58398-47050  | COVER, REAR FLOOR UNDER , RH           | 0.00     | \$175.10        | 0.00         | \$0.00           | Replace            | Not Given         |

✓ RE  
X NN  
✓ NEC  
✓ NEC  
✓ NEC  
✓ NEC  
✓ NEC  
X NN  
✓ NEC  
✓ CUT  
X NN  
X NN  
X NN  
X NN

**STRIDES Accident Vehicle Repair Estimates**

|                                                   |
|---------------------------------------------------|
| <b>STRIDES Automotive Services Pte Ltd</b>        |
| 60 Woodlands Industrial Park E4, Singapore 757705 |
| FAX Number : 63685592                             |
| Estimator Telephone Number : 68662623             |
| Accident Reporting Number : 68662672              |

Date Generated : 03/01/2022

User ID PohSuan

|              |  |                |                                           |      |                   |      |                 |         |           |   |    |
|--------------|--|----------------|-------------------------------------------|------|-------------------|------|-----------------|---------|-----------|---|----|
|              |  | 58399-47030    | COVER, REAR FLOOR UNDER , LH              | 0.00 | \$241.90          | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 66259-47010    | COVER, REAR FLOOR UNDER CENTER            | 0.00 | \$229.90          | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 81551-47481    | LENS & BODY, REAR COMBINATION LAMP , RH   | 0.00 | \$339.60          | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 81561-47471    | LENS & BODY, REAR COMBINATION LAMP , LH   | 0.00 | \$339.60          | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 81497-47040    | COVER, REAR COMBINATION LAMP, RH          | 0.00 | \$69.90           | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 81498-47040    | COVER, REAR COMBINATION LAMP, LH          | 0.00 | \$69.90           | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 81457-47020    | LENS & BODY, REAR COMBINATION LAMP, NO.2  | 0.00 | \$261.00          | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 81456-47020    | LENS & BODY, REAR COMBINATION LAMP, NO.2  | 0.00 | \$261.00          | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 81580-47070    | LAMP ASSY, REAR, RH                       | 0.00 | \$293.60          | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 81590-47070    | LAMP ASSY, REAR, LH                       | 0.00 | \$293.60          | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  |                | SENSOR REVERSE                            | 0.00 | \$180.00          | 0.00 | \$0.00          | Replace | Check     | X | NN |
|              |  | 89997-30100    | ANTENNA, ELECTRICAL KEY                   | 0.00 | \$72.00           | 0.00 | \$0.00          | Replace | Check     | X | NN |
|              |  | 58307-47100    | END PANEL SUB-ASSY, BODY LOWER BACK       | 0.00 | \$651.00          | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  |                | SEALANT SIKAFLEX                          | 0.00 | \$37.00           | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 76801-47170-A1 | TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-  | 0.00 | \$913.60          | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 75403-48010    | EMBLEM SUB-ASSY REAR                      | 0.00 | \$47.90           | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 75441-47220    | NAME PLATE (HYBRID) , LUGGAGE COMPARTMENT | 0.00 | \$54.60           | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 75442-47200    | NAME PLATE (PRIUS) , LUGGAGE COMPARTMENT  | 0.00 | \$54.60           | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  |                | STRIDES LOGO                              | 0.00 | \$7.80            | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  |                | STICKER DECAL 65558888                    | 0.00 | \$21.60           | 0.00 | \$0.00          | Replace | Not Given | X | NN |
|              |  | 76085-47916    | SPOILER SUB-ASSY, REAR                    | 0.00 | \$1,575.40        | 0.00 | \$0.00          | Replace | Not Given | X | NN |
| <b>Total</b> |  |                |                                           |      | <b>\$7,661.80</b> |      | <b>\$749.03</b> |         |           |   |    |

**Added Spare Parts / Material Usage After Surveyor Signed off**

| Part Number  | Portion | Stock Number | Part Name | Quantity | List Price \$ | Discount (%) | Final Price (\$) | ARC Check | Surveyor Check |
|--------------|---------|--------------|-----------|----------|---------------|--------------|------------------|-----------|----------------|
| <b>Total</b> |         |              |           |          |               |              |                  |           |                |

|   |                 |
|---|-----------------|
|   | 749.03          |
| + | 200.00          |
| + | 230.00          |
|   | <u>1,179.03</u> |