

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC1325X

8/12/2021

MAKE REG 03.09.2018

CHIANG/CHINA

MODEL IONIQ G2

Qty	Parts Description/ Labour	Type	Amount
1	REAR BUMPER		\$459.40
1	REAR BUMPER SIDE BRACKET RH		\$55.80
1	REAR BUMPER REINFORCEMENT		\$394.80
1	REAR BUMPER CENTRE MOULDING		\$451.25
1	REAR BUMPER REFLECTOR RH		\$41.45
1	ANTENNA SMART KEY SENSOR		\$40.50
1	REAR FOG LAMP		\$201.50
10	REAR BUMPER CLIPS		\$22.00
	SUB TOTAL		\$1,666.70
	20.00%		\$333.34
	DISCOUNTED TOTAL		\$1,333.36
1	REAR REVERSE SENSOR		\$180.00
1	REAR NUMBER PLATE W/HOLDER		\$55.00
			\$235.00
	Labour Charge		
	Panel Beating		\$500.00
	Spray Painting Charge		\$400.00
	Check Lighting and Wiring		\$60.00
	Tuff Kote		\$90.00
	Remove/refix Reverse sensor		\$60.00
	TOTAL LABOUR		\$1,110.00
	ESTIMATE TOTAL		\$2,678.36
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Tanphie 97495749
 inp' 28/12/21 @ 430
 c/s Mary after repair
 2 days
 fupri @ 44kanfom

Date/Time: 28.12.2021 12:40

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4156806

JC NO: 305499531

STOMER

COMFORT TRANSPORTATION PTE LTD
/MS 7010045
STOMER NO. 383 SIN MING DRIVE
DRESS Singapore SINGAPORE 575717
65508755 (R) (O)
(P)

COUNT CARD NO.

REGN NO: SHC1325X

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL: IONIQ(G2)

DATE/TIME IN: 28.12.2021 09:55

YR OF MANU: 03.09.2018

TARGET DATE

CHASSIS CODE: KMHC851CVKU107405

COMPLETION DATE/TIME:


JOB DESCRIPTION

Accident Date: 27.12.2021

ATURE: 3P 27.12.2021

3/NO LABOR CODE

DESCRIPTION



ECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

Exit Pass

3:

Vehicle No.: SHC1325X

C

Vehicle No.: SHC1325X

le No.:

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard